

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY

INTERNAL PHOTOGRAPHS




Figure 1. Equipment under Test (cover removed)

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY




Figure 2. Top of primary PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY




Figure 3. Bottom of Primary PCB with radio PCB and Camera removed from housing

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY




Figure 4. Bottom of primary PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY




Figure 5. Radio PCB removed from sub-housing (Top of radio PCB)

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Subpart C, Part 15.247
2A8GI-V1FRSKY
26-0131
June 26, 2026
Rocket Drones
V1 FRSKY




Figure 6. Bottom of radio PCB and Antenna