

Super Micro Computer, Inc.

980 Rock Avenue, San Jose, CA 95131, USA
Tel: (408) 503-8000 6297 ; Fax: (408) 503-8008

We hereby declare the only difference between [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) and [FCC ID: 2AEVX-E100TDE3 \(IC: 20273-E100TDE3\)](#) is the integrated Wi-Fi module. The WWAN module/PCB/Antenna design of [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) are identical to those in [FCC ID: 2AEVX-E100TDE3 \(IC: 20273-E100TDE3\)](#).

The only difference between [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) and [FCC ID: 2AEVX-E100THAW \(IC: 20273-E100THAW\)](#) is the integrated WWAN module. The Wi-Fi module/PCB/Antenna design of [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) are identical to those in [FCC ID: 2AEVX-E100THAW \(IC: 20273-E100THAW\)](#)

Base on the similarity addressed above, we hereby request to leverage the test data of [FCC ID: 2AEVX-E100TDE3 \(IC: 20273-E100TDE3\)](#) and [FCC ID: 2AEVX-E100THAW \(IC: 20273-E100THAW\)](#) to demonstrate the compliance of [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) regarding to FCC Part 15C,22H,24E /IC RSS-247,RSS-132, RSS-133 requirements. The worst cases found in [FCC ID: 2AEVX-E100TDE3 \(IC: 20273-E100TDE3\)](#) and [FCC ID: 2AEVX-E100THAW \(IC: 20273-E100THAW\)](#) are verified on [FCC ID: 2AEVX-E100TDAW \(IC: 20273-E100TDAW\)](#) to ensure compliance is kept.

Should you have any comments or questions, please feel free to contact me.

Sincerely,



Victor Yuan
victor.yuan@supermicro.com