














ANTO_802.11ax_HE40_106T_High_UNII 5






ANTO_802.11ax_HE40_106T_High_UNII 6





ANTO_802.11ax_HE40_106T_High_UNII 7






ANTO_802.11ax_HE40_106T_High_UNII 8






ANT1_802.11ax_HE40_106T_High_UNII 5






ANT1_802.11ax_HE40_106T_High_UNII 6





ANT1_802.11ax_HE40_106T_High_UNII 7






ANT1_802.11ax_HE40_106T_High_UNII 8






ANTO_802.11ax_HE40_242T_Low_UNII 5



ANTO_802.11ax_HE40_242T_Low_UNII 6



ANTO_802.11ax_HE40_242T_Low_UNII 7






ANTO_802.11ax_HE40_242T_Low_UNII 8





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (256) / (427) Pages



ANT1_802.11ax_HE40_242T_Low_UNII 5






ANT1_802.11ax_HE40_242T_Low_UNII 6






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (257) / (427) Pages





ANT1_802.11ax_HE40_242T_Low_UNII 7






ANT1_802.11ax_HE40_242T_Low_UNII 8






ANTO_802.11ax_HE40_242T_High_UNII 5






ANTO_802.11ax_HE40_242T_High_UNII 6





ANTO_802.11ax_HE40_242T_High_UNII 7






ANTO_802.11ax_HE40_242T_High_UNII 8






ANT1_802.11ax_HE40_242T_High_UNII 5






ANT1_802.11ax_HE40_242T_High_UNII 6





ANT1_802.11ax_HE40_242T_High_UNII 7






ANT1_802.11ax_HE40_242T_High_UNII 8






ANTO_802.11ax_HE40_484T_UNII 5






ANTO_802.11ax_HE40_484T_UNII 6





ANTO_802.11ax_HE40_484T_UNII 7



ANTO_802.11ax_HE40_484T_UNII 8



ANT1_802.11ax_HE40_484T_UNII 5






ANT1_802.11ax_HE40_484T_UNII 6






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (265) / (427) Pages



ANT1_802.11ax_HE40_484T_UNII 7





ANT1_802.11ax_HE40_484T_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-00952
Page (266) / (427) Pages





ANT0_802.11ax_HE80_26T_Low_UNII 5



ANT0_802.11ax_HE80_26T_Low_UNII 6



ANT0_802.11ax_HE80_26T_Low_UNII 7



ANT0_802.11ax_HE80_26T_Low_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501



Report No.:
CTK-2023-00952
Page (268) / (427) Pages





ANT1_802.11ax_HE80_26T_Low_UNII 5



ANT1_802.11ax_HE80_26T_Low_UNII 6



ANT1_802.11ax_HE80_26T_Low_UNII 7






ANT1_802.11ax_HE80_26T_Low_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (270) / (427) Pages





ANT0_802.11ax_HE80_26T_Mid_UNII 5



ANT0_802.11ax_HE80_26T_Mid_UNII 6



ANT0_802.11ax_HE80_26T_Mid_UNII 7






ANT0_802.11ax_HE80_26T_Mid_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (272) / (427) Pages





ANT1_802.11ax_HE80_26T_Mid_UNII 5



ANT1_802.11ax_HE80_26T_Mid_UNII 6



ANT1_802.11ax_HE80_26T_Mid_UNII 7




ANT1_802.11ax_HE80_26T_Mid_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (274) / (427) Pages





ANT0_802.11ax_HE80_26T_High_UNII 5



ANT0_802.11ax_HE80_26T_High_UNII 6



ANTO_802.11ax_HE80_26T_High_UNII 7



ANTO_802.11ax_HE80_26T_High_UNII 8



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (276) / (427) Pages



ANT1_802.11ax_HE80_26T_High_UNII 5






ANT1_802.11ax_HE80_26T_High_UNII 6





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2023-00952
Page (277) / (427) Pages



ANT1_802.11ax_HE80_26T_High_UNII 7






ANT1_802.11ax_HE80_26T_High_UNII 8




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2023-00952
Page (278) / (427) Pages





ANT0_802.11ax_HE80_52T_Low_UNII 5



ANT0_802.11ax_HE80_52T_Low_UNII 6



ANT0_802.11ax_HE80_52T_Low_UNII 7



ANT0_802.11ax_HE80_52T_Low_UNII 8