

INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)



INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)




INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)



INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)



INTERTEK TESTING SERVICE

Report No: 18120746HKG-001
18120746HKG-002
18120746HKG-003
18120746HKG-004

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Back View)

