

## **INTERTEK TESTING SERVICE**


---

Report No:19091333HKG-005  
19091333HKG-006  
19091333HKG-007  
19091333HKG-008

### **Configuration Photographs**

#### **Worst-Case Line-Conducted Emissions**

**(Front View)**



## INTERTEK TESTING SERVICE

---

Report No:19091333HKG-005  
19091333HKG-006  
19091333HKG-007  
19091333HKG-008

### Configuration Photographs

#### Worst-Case Line-Conducted Emissions

(Back View)



## **INTERTEK TESTING SERVICE**

---

Report No:19091333HKG-005

19091333HKG-006

19091333HKG-007

19091333HKG-008

### **Configuration Photographs**

#### **Worst-Case Line-Conducted Emissions**

**(Back View)**



## **INTERTEK TESTING SERVICE**

---

Report No:19091333HKG-005

19091333HKG-006

19091333HKG-007

19091333HKG-008

### **Configuration Photographs**

#### **Worst-Case Line-Conducted Emissions**

**(Front View)**



## INTERTEK TESTING SERVICE

---

Report No:19091333HKG-005  
19091333HKG-006  
19091333HKG-007  
19091333HKG-008

### Configuration Photographs

#### Worst-Case Line-Conducted Emissions

(Back View)



## **INTERTEK TESTING SERVICE**

---

Report No:19091333HKG-005

19091333HKG-006

19091333HKG-007

19091333HKG-008

### **Configuration Photographs**

#### **Worst-Case Line-Conducted Emissions**

**(Back View)**

