

FCC ID: EZZ5PI613805

TX RX SYSTEMS, INC.

Sample of FCC Label

IC: 1940A-PI613805

TX RX SYSTEMS, INC.

Sample of IC Label

SERIAL# XXXXX-X
61-38-05

TX RX SYSTEMS, INC.

FCC ID: EZZ5PI613805

TX RX SYSTEMS, INC.



SERIAL# XXXXX-X
61-38-05

TX RX SYSTEMS, INC.

IC: 1940A-PI613805

TX RX SYSTEMS, INC.

SERIAL# XXXXX-X
61-38-05251-G1

TX RX SYSTEMS, INC.

IC: 1940A-PI613805

TX RX SYSTEMS, INC.

CAUTION

Signal Boosters are high gain devices that can be damaged if certain details are overlooked before the initial operation.

There is one item to note before use:

1. The major cause of damage to signal boosters is the amplification of input RF power levels in excess of the maximum safe input. The maximum input levels for this unit are listed at the input/output ports.
2. Signal Boosters may start to self-oscillate if the location between the two THICK FREQUENCY INPUT / LOW FREQUENCY OUTPUT ports (i.e. antennas, including cables, distribution devices), is not greater than the signal booster gain. The minimum separation between the two cables, which is related to the two signal booster antennas is recommended to be 21 dB greater than the gain of the signal booster, specify for this unit is 21 dB.

You are encouraged to refer to the additional cautionary notes published in the installation and setup manual. Additionally, further explanations to the above points are discussed.

1 1/4"

9"