



M. Flom Associates, Inc. - Global Compliance Center

3356 North San Marcos Place, Suite 107, Chandler, Arizona 85225-7176

www.mflom.com general@mflom.com (480) 926-3100, FAX: 926-3598

October 20, 2003

Applicant: Wulfsberg Electronics Division
Equipment: FCC ID: FRW2000-800
Reference: Job #1388UC3

Please note that the FCC ID has only one set of 'FRW' (on all the correspondence from Timco, the Grantee code has been repeated)

- 1) Attached please find Tune-up Procedures, Circuit Descriptions of the ITM, Schematics and BOM of the transmitter boards.
- 2) Attached please find new Internal Photos.
- 3) Please find amended MPE page attached.
- 4) Attached please find MPE label.
- 5) The 100 cm separation distance was incorrectly given. It should have been 30 cm as shown on page 6 of the Environmental Assessment report. The 100 cm was the effect of various configurations shown on pages 8, 10 and 12. Please find corrected 'Mandatory Safety Instructions to Installers and Users' which will appear in the manual.
- 6) Please see corrected pages 12 and 13.