


APPENDIX K: TEST PHOTOGRAPHS – PLASTIC HOUSING




PHOTOGRAPH 6: RADIATED EMISSIONS FRONT VIEW; WORST CASE CONFIGURATION



PHOTOGRAPH 7: RADIATED EMISSIONS REAR VIEW; WORST CASE CONFIGURATION



PHOTOGRAPH 8: CONDUCTED EMISSIONS FRONT VIEW



PHOTOGRAPH 9: CONDUCTED EMISSIONS REAR VIEW

APPENDIX L: TEST PHOTOGRAPHS - METAL HOUSING



PHOTOGRAPH 10: RADIATED EMISSIONS FRONT VIEW; WORST CASE CONFIGURATION



PHOTOGRAPH 11: RADIATED EMISSIONS REAR VIEW; WORST CASE CONFIGURATION



PHOTOGRAPH 12: CONDUCTED EMISSIONS FRONT VIEW



PHOTOGRAPH 13: CONDUCTED EMISSIONS REAR VIEW