



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 29, 2003

RE: Askey Computer Corporation

FCC ID: H8NWLL3050

I have a few comments on this Application.

- 1.) The Block Diagram does not meet the minimum requirements of 2.1033(b)(5). Please submit revised exhibit.
- 2.) The Manual contains none of the compliance information required by the FCC. No Grant can or will be issued until these issues are resolved. Please provide updated manual addressing the following issues:
 - a. 15.21 information to user
 - b. Hardware installation instructions for OEM integrators
 - c. Caution against providing installation instructions to consumer
 - d. Prohibitions on co-location
- 3.) Is a plot missing on Page 34 of the Test Report?
- 4.) Is a plot missing on Page 58 of the Test Report?

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.