

Response to TCB Findings

1. The label is missing the 15.121(f) warning statement. This is a requirement.

[Revised label supplied with the statement.](#)

2. The ferrite on the power cord listed in the report is not mentioned in the manual. How will this be supplied to the end users? If the manufacturer is planning to incorporate this ferrite to all the power supply cables, then a warning about not to remove the ferrites on both the power cable and the serial cable is required. Users should also be warned about not to use any substitutes for these cables.

[Page ii of the manual revised. Warnings included in the "Caution" section.](#)