

Subject: Sercel questions
Date: Sun, 28 Jul 2002 23:27:18 -0500
From: "Brad Rehm" <brehm@texas.net>
To: <dennis@yosemite.net>

Dennis,

Nicole brought a copy of your email to me a few minutes ago. I can answer both of the questions you ask, but you may want to suggest other ways of handling them.

The RF exposure statement is at the end of Section 7 of the report. It reads:

"Warning: Maximum Permissible Exposure to RF energy may be exceeded if the transmitter is activated while personnel are within two (2) meters of the antenna. Do not operate the transmitter while personnel are within two (2) meters of the antenna."

You may already have seen this text, and you may be asking why it doesn't appear in the excerpts we've included of the manual. The reason is that although the new text has been added to the source version of the manual, the printed version isn't available yet. I can find out when this will be available if you need it.

The tune-up procedure is in Appendix F. There is a reference to it at the end of Section 3:

"To achieve this occupied bandwidth, the transmitter deviation is adjusted to 7 kHz. The manufacturing procedure used at Sercel is presented in Appendix D."

As you can see, it is incorrectly labeled Appendix D. This is my fault, and I've corrected the error. The change will be in the final version of the report, which will also contain some text and the photograph of the equipment configuration on the OATS.

Hope this helps.

Brad
brehm@texas.net
PTI