

Chris Harvey

From: MLTLab [mltlab@seed.net.tw]
Sent: Monday, February 02, 2004 5:39 PM
To: charvey-tcb@CCSEMC.com
Cc: Country Huang
Subject: Fw: ??: Fw: Need Information AN04T3576 FCC ID: M8CTP10

Importance: High



REPORTN.pdf (1
MB)

Dear Chris,

Please be informed that we have revised the report as you request on your web site. At the meanwhile, please find the attachment of revised report for your reference.

Please let us know if you have any questions for the revised report. Thanks for your help.

With Best Regards,
Patty Huang

> From: "Chris Harvey" <charvey-tcb@CCSEMC.com>
> To: <mltlab@seed.net.tw>; "Chris Harvey" <charvey-tcb@CCSEMC.com>
> Cc: <tech@mlt.com.tw>
> Sent: Wednesday, January 28, 2004 8:29 AM
> Subject: RE: ??: Fw: Need Information AN04T3576 FCC ID: M8CTP10
>
>
> > Patty, yes pleased include that statement in the report along with a
time
> > period as measured. If there is a time period, such as the
> > transmitter stops transmitting 100msec after release of button then
> > add that measurement. If it stops transmitting much less than 5
> > seconds, then
> please
> > state that.
> >
> > I hope this is helpful,
> >
> > Chris harvey
> > -----Original Message-----
> > From: mltlab@seed.net.tw [mailto:mltlab@seed.net.tw]
> > Sent: Tuesday, January 27, 2004 11:19 AM
> > To: charvey-tcb@CCSEMC.com
> > Cc: tech@mlt.com.tw
> > Subject: ??: Fw: Need Information AN04T3576 FCC ID: M8CTP10
> >
> > Dear Chris,
> >
> > Please kindly advise that the following statement is added on the
> > report if accepted. Thanks for your help.

> >
> >
> > 7.4.7. Verification of De-activation after 5 seconds
> > This device stops transmitting once the activation button in
> > depressed.
> >
> >
> > Looking forward to having your advise.
> >
> > With Best Regards,
> > Patty Huang
> >
> >
> >
> > ----- Original Message -----
> > From: "Chris Harvey" <charvey-tcb@CCSEMC.com>
> > To: <tech@mlt.com.tw>
> > Cc: "Mike Kuo" <MKUO@CCSEMC.com>
> > Sent: Friday, January 16, 2004 12:25 AM
> > Subject: FW: Need Information AN04T3576 FCC ID: M8CTP10
> >
> >
> > > The review of the above referenced application has been performed.
> > >
> > > I could not locate a measurement or compliance statement of
> > > compliance
> > > with
> > > the requirements of FCC 15.231(a)(1), copied below. Please
> > > provide
> > > this
> > > information:
> > > 15.231(a)(1): A manually operated transmitter shall employ a
> > > switch that will automatically deactivate the transmitter within
> > > not more
> > > than
> > > 5 seconds of being released.
> > >
> > > The items indicated above must be submitted before processing can
> > > continue
> > > on the above referenced application. Failure to provide the
> > > requested information within 30 days of the original e-mail date
> > > may result in application dismissal and forfeiture of the filing
> > > fee. Also, please
> > > note
> > > that partial responses increase processing time and should not be
> > > submitted.
> > > Any questions about the content of this correspondence should be
> > > directed
> > > to
> > > the e-mail address listed below the name of the sender.
> > >
> > > Please respond directly to charvey-tcb@ccsemc.com
> > >
> > > Best regards,
> > >
> > > Chris Harvey
> > > Charvey-tcb@ccsemc.com
> > > 443-622-3300
> > >

> >
> >
> >
> > ----- ?????? -----
> >
> >
> >
> >
> >
> > -----
> > This mail sent through Seednet Webmail <http://webmail.seed.net.tw>
> >
>