


INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)




INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)




INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs Worst-Case Radiated Emissions

(Front View)




INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)




INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Conducted Emissions

(Front View)




INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Conducted Emissions

(Right View)



INTERTEK TESTING SERVICE

Report No: 15081213HKG-002

Configuration Photographs

Worst-Case Conducted Emissions

(Left View)

