

TCB Review Comments for (3Com FCC ID:O9C-WL565)

-EMC-

Question #1: User manual p43; Power show on the page are 20dBm, but report measured 17dBm (50.12mw) max. Please clarify and make necessary correction.

Question #2: Test report P7; Per FCC part 15.203, all intentional radiator shall use unique coupling device on antenna jack or connector. However, this device seems incorporated a non-unique standard N-type connector on the antenna port. Please confirm and make necessary change.

Question #3: FRN not matching the Form 731 info.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best Regards

Steve Cheng / Technical Reviewer TCB/FCB/NB
North American EMC Certification Service Inc.
Email: steve.cheng@nacsemc.com
Tel: 403-241-8826