

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 1 of 6

Contents

<i>Photograph 1</i>	<i>Conducted - Galvanised Unit Front (1)</i>	2
<i>Photograph 2</i>	<i>Conducted - Galvanised Unit Front (2)</i>	2
<i>Photograph 3</i>	<i>Conducted - Galvanised Unit Back</i>	3
<i>Photograph 4</i>	<i>Conducted - Stainless Unit Front (1)</i>	3
<i>Photograph 5</i>	<i>Conducted - Stainless Unit Front (2)</i>	4
<i>Photograph 6</i>	<i>Conducted - Stainless Unit Back</i>	4
<i>Photograph 7</i>	<i>Radiated below 30MHz - Galvanised Unit</i>	5
<i>Photograph 8</i>	<i>Radiated below 30MHz - Stainless Unit</i>	5
<i>Photograph 9</i>	<i>Radiated above 30MHz - Front</i>	6
<i>Photograph 10</i>	<i>Radiated above 30MHz - Back</i>	6

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 2 of 6



Photograph 1 Conducted - Galvanised Unit Front (1)



Photograph 2 Conducted - Galvanised Unit Front (2)

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 3 of 6



Photograph 3 Conducted - Galvanised Unit Back



Photograph 4 Conducted - Stainless Unit Front (1)

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 4 of 6



Photograph 5 Conducted - Stainless Unit Front (2)



Photograph 6 Conducted - Stainless Unit Back

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 5 of 6



Photograph 7 Radiated below 30MHz - Galvanised Unit



Photograph 8 Radiated below 30MHz - Stainless Unit

	Report No: R1321	FCC ID: PCZ1100	
	Test No: T0284	Test Photographs	Page: 6 of 6



Photograph 9 Radiated above 30MHz - Front



Photograph 10 Radiated above 30MHz - Back