



UL Apex Co., Ltd.

Head Office
4383-326 Asama-cho, Ise-shi,
Mie 516-0021 Japan
TEL: 0596-24-6717
FAX: 0596-24-8020
<http://www.ulapex.jp>

Date: August 10, 2004

RE: CONTEC CO., LTD.

FCC ID: PQRDS540-APDL

Dear Mr. Dennis Ward,

Regarding the above referenced application, please find our reply to your comments dated August 8, 2004:

- 1) We corrected Equipment code in Form 731. Please refer to revised Form 731 for 15.247.
- 2) Thank you very much for your advice.
- 3) Antenna and connector are installed by professionals.

(ATCB comments - per FCC training and FCC staff – antenna connectors located inside the case which is not accessible to user meets criteria – see TCB training slides)

- 4) We will provide the documents showing the compliance to 15.407(c).
- 5) Testing was done in accordance with FCC rules. The value described in operational manual is just a reference data based on the test with RBW/VBW settings mentioned in page 5 of Operational Description.

We hope the above reply is satisfactory.

If any problems, please let us know.

Best regards,

Yukari Ito (Ms.)

UL Apex Co., Ltd.

