

E04-000040-2

1. The Direct Connect manual was mistakenly uploaded for this product.
Please delete it from the submittal.
2. An RF test report has been uploaded.