

Non-Conformity or Comment	Submitted Response
The power output measured in the test report differs from that shown on the grant. Please explain how this equipment qualifies for PCII / rule part change.	Test laboratory discovered inaccurate test report during original certification. The original output power measurements omitted the correction for an included attenuator (shown in setup photos). When the original measurements are corrected for the attenuator, the power output measurements match within a small margin. Therefore the output power is confirmed to remain consistent from the time of original testing.