



October 21, 2019

Regarding ROR00000006 Part 96 application:

There is no tuneup procedure provided to the installer or user of the device. Tuning is performed at the factory.

Sincerely,

A handwritten signature in blue ink, appearing to read "Jim Dickerman". The signature is fluid and cursive, with a large initial "J" and "D".

Jim Dickerman

Vice President of Engineering

BLiNQ Wireless