



Continental Wireless, Inc.

2355 Merritt Drive / Suite #200 Garland TX 75041
Tel 972-926-7443/800-527-2000 Fax #972-926-0624

Attn: Reviewing Engineer

Federal Communications Commission

7435 Oakland Mills Road

Columbia, MD 21046

RE: Tune-up Procedure for R5000-O-4.9, FCC ID TIG R5000-O-49

To Whom It May Concern:

We the undersigned state that the equipment known as the InfiNet R5000-O-4.9 wireless router, FCC ID TIG R5000-O-49 has no field adjustable hardware adjustment points. All adjustments, and configuration changes, are made via software, as described in the user manual for this equipment. Therefore we are not submitting a separate tune-up procedure for this equipment.

Please contact me if there is any information you may need.

Sincerely,

Gary Weber
Vice President
Continental Wireless, Inc.