

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
WPEPSASII-04
8031A-PSASII04
23-0218
April 22, 2024
Copeland
PSASII-04

INTERNAL PHOTOGRAPHS




Figure 4. PSASII-04 Radio module (Component Side)

Note: The trace antenna is disabled for this application.

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
WPEPSASII-04
8031A-PSASII04
23-0218
April 22, 2024
Copeland
PSASII-04




Figure 5. PSASII-04 Radio module (Bottom Side)

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
WPEPSASII-04
8031A-PSASII04
23-0218
April 22, 2024
Copeland
PSASII-04




Figure 2. PSASII-04 Radio module installed on HOST Device interface board

-Radio module identified with RED dashed lines.

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
WPEPSASII-04
8031A-PSASII04
23-0218
April 22, 2024
Copeland
PSASII-04




Figure 3. HOST Device interface board with radio module removed.