


- 5) Please confirm the same antenna element was used as the original approval. The original shows:



- 7) This result is nearly 14 dB lower than the original. Is this expected? was various positions of the TX antenna investigated?

Also note that the NFC output level was significantly reduced by the addition of the dampening resistor added to the antenna. The coil has remained the same.