9.1.8. LTE BAND 26 AND 5G NR n26 (PART 90S)

LTE BAND 26 (PART 90S)



LTE B26 1.4MHz QPSK Middle Channel RB6-0, ID:27979



LTE B26 3MHz QPSK Middle Channel RB15-0, ID:27979



LTE B26 5MHz QPSK Middle Channel RB25-0, ID:27979



LTE B26 10MHz QPSK Middle Channel RB50-0, ID:27979



LTE B26 10MHz QPSK Middle Channel RB1-0, ID:27979

Intentionally Blank

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n26 (PART 90S)



5G NR n26 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n26 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n26 10MHz BPSK Middle Channel RB1-0, ID:50822

Intentionally Blank

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.9. LTE BAND 26 AND 5G NR n26 (PART 22)

LTE BAND 26



LTE B26 1.4MHz QPSK Middle Channel RB6-0, ID:27979



LTE B26 3MHz QPSK Middle Channel RB15-0, ID:27979



LTE B26 5MHz QPSK Middle Channel RB25-0, ID:27979



LTE B26 10MHz QPSK Middle Channel RB50-0, ID:27979



LTE B26 15MHz QPSK Middle Channel RB75-0, ID:27979



LTE B26 15MHz QPSK Middle Channel RB1-0, ID:27979

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n26 (PART 22)



5G NR n26 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n26 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n26 15MHz BPSK Middle Channel RB75-0, ID:50822



5G NR n26 20MHz BPSK Middle Channel RB100-0, ID:50822



5G NR n26 20MHz Middle High Channel RB1-0, ID:50822

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.10. LTE BAND 30 AND 5G NR n30

LTE BAND 30



LTE B30 5MHz QPSK Middle Channel RB25-0, ID:39005



LTE B30 10MHz QPSK Middle Channel RB50-0, ID:39005



LTE B30 10MHz QPSK Middle Channel RB1-0, ID:39005

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n30



5G NR n30 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n30 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n30 10MHz BPSK Middle Channel RB1-0, ID:50822

Intentionally Blank

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.11. LTE BAND 41 AND 5G NR n41 HPUE

LTE BAND 41



LTE B41 5MHz QPSK Middle Channel RB25-0, ID:50822



LTE B41 10MHz QPSK Middle Channel RB50-0, ID:50822



LTE B41 15MHz QPSK Middle Channel RB75-0, ID:50822



LTE B41 20MHz QPSK Middle Channel RB100-0, ID:50822



LTE B41 20MHz QPSK Middle Channel RB1-0, ID:39005

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n41



5G NR n41 10MHz BPSK Middle Channel RB24-0, ID:27966



5G NR n41 15MHz BPSK Middle Channel RB36-0, ID:27966



5G NR n41 20MHz BPSK Middle Channel RB50-0, ID:27966



5G NR n41 25MHz BPSK Middle Channel RB64-0, ID:27966



5G NR n41 30MHz BPSK Middle Channel RB75-0, ID:27966



5G NR n41 40MHz BPSK Middle Channel RB100-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK Middle Channel RB128-0, ID:27966



5G NR n41 60MHz BPSK Middle Channel RB162-0, ID:27966



5G NR n41 70MHz BPSK Middle Channel RB180-0, ID:27966



5G NR n41 80MHz BPSK Middle Channel RB216-0, ID:27966



5G NR n41 90MHz BPSK Middle Channel RB243-0, ID:27966



5G NR n41 100MHz BPSK Middle Channel RB270-0, ID:27966

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 100MHz BPSK Middle Channel RB1-0, ID:27966

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.12. LTE BAND 48 AND 5G NR n48

LTE BAND 48



LTE B48 5MHz QPSK Middle Channel RB25-0, ID:39005



LTE B48 10MHz QPSK Middle Channel RB50-0, ID:39005



LTE B48 15MHz QPSK Middle Channel RB75-0, ID:39005



LTE B48 20MHz QPSK Middle Channel RB100-0, ID:39005



LTE B48 20MHz QPSK Middle Channel RB1-0, ID:39005

Intentionally Blank

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n48



5G NR n48 10MHz BPSK Middle Channel RB24-0, ID:27966



5G NR n48 15MHz BPSK Middle Channel RB36-0, ID:27966



5G NR n48 20MHz BPSK Middle Channel RB50-0, ID:27966



5G NR n48 30MHz BPSK Middle Channel RB75-0, ID:27966

5G NR n48 40MHz BPSK Middle Channel RB100-0, ID:27966



5G NR n48 40MHz BPSK Middle Channel RB1-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.13. LTE BAND 66 AND 5G NR n66

LTE BAND 66



LTE B66 1.4MHz QPSK Middle Channel RB6-0, ID:39005



LTE B66 3MHz QPSK Middle Channel RB15-0, ID:39005



LTE B66 5MHz QPSK Middle Channel RB25-0, ID:39005



LTE B66 10MHz QPSK Middle Channel RB50-0, ID:39005



LTE B66 15MHz QPSK Middle Channel RB75-0, ID:39005



LTE B66 20MHz QPSK Middle Channel RB100-0, ID:39005

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B66 20MHz QPSK Middle Channel RB1-0, ID:39005

Intentionally Blank

5G NR n66



5G NR n66 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n66 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n66 15MHz BPSK Middle Channel RB75-0, ID:50822



5G NR n66 20MHz BPSK Middle Channel RB100-0, ID:50822

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n66 25MHz BPSK Middle Channel RB128-0, ID:50822



5G NR n66 30MHz BPSK Middle Channel RB160-0, ID:50822



5G NR n66 40MHz BPSK Middle Channel RB216-0, ID:50822



5G NR n66 40MHz BPSK Middle Channel RB1-0, ID:50822

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.14. 5G NR n70



5G NR n70 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n70 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n70 15MHz BPSK Middle Channel RB75-0, ID:50822



5G NR n70 15MHz BPSK Middle Channel RB1-0, ID:50822

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.15. LTE BAND 71 AND 5G NR n71

LTE BAND 71



LTE B71 5MHz QPSK Middle Channel RB25-0, ID:19210



LTE B71 10MHz QPSK Middle Channel RB50-0, ID:19210



LTE B71 15MHz QPSK Middle Channel RB75-0, ID:19210



LTE B71 20MHz QPSK Middle Channel RB100-0, ID:19210



LTE B71 20MHz QPSK Middle Channel RB1-0, ID:19210

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

5G NR n71



5G NR n71 5MHz BPSK Middle Channel RB25-0, ID:50822



5G NR n71 10MHz BPSK Middle Channel RB50-0, ID:50822



5G NR n71 15MHz BPSK Middle Channel RB75-0, ID:50822



5G NR n71 20MHz BPSK Middle Channel RB100-0, ID:50822



5G NR n71 20MHz BPSK Middle Channel RB1-0, ID:50822

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

9.1.16. 5G NR n77 (Part 27 3450-3550MHz) HPUE



5G NR n77 10MHz BPSK Middle Channel RB24-0, ID:27966



5G NR n77 15MHz BPSK Middle Channel RB36-0, ID:27966



5G NR n77 20MHz BPSK Middle Channel RB50-0, ID:27966



5G NR n77 25MHz BPSK Middle Channel RB64-0, ID:27966



5G NR n77 30MHz BPSK Middle Channel RB75-0, ID:27966



5G NR n77 40MHz BPSK Middle Channel RB100-0, ID:27966

UL VERIFICATION SERVICES INC. FORM NO: CCSUP4031B
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n77 50MHz BPSK Middle Channel RB128-0, ID:27966



5G NR n77 60MHz BPSK Middle Channel RB162-0, ID:27966



5G NR n77 70MHz BPSK Middle Channel RB180-0, ID:27966



5G NR n77 80MHz BPSK Middle Channel RB216-0, ID:27966



5G NR n77 90MHz BPSK Middle Channel RB243-0, ID:27966



5G NR n77 100MHz BPSK Middle Channel RB270-0, ID:27966

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

 5G NR n77 100MHz BPSK Middle Channel RB1-0, ID:27966	Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.