

LTE B7 10MHz QPSK Middle Channel RB1-0



LTE B7 10MHz 16QAM Middle Channel RB1-0



LTE B7 10MHz QPSK Middle Channel RB1-49



LTE B7 10MHz 16QAM Middle Channel RB1-49



LTE B7 10MHz QPSK Middle Channel RB50-0



LTE B7 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 10MHz QPSK High Channel RB1-0



LTE B7 10MHz 16QAM High Channel RB1-0



LTE B7 10MHz QPSK High Channel RB1-49



LTE B7 10MHz 16QAM High Channel RB1-49



LTE B7 10MHz QPSK High Channel RB50-0



LTE B7 10MHz 16QAM High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK Low Channel RB1-0



LTE B7 15MHz 16QAM Low Channel RB1-0



LTE B7 15MHz QPSK Low Channel RB1-74



LTE B7 15MHz 16QAM Low Channel RB1-74



LTE B7 15MHz QPSK Low Channel RB75-0



LTE B7 15MHz 16QAM Low Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK Middle Channel RB1-0



LTE B7 15MHz 16QAM Middle Channel RB1-0



LTE B7 15MHz QPSK Middle Channel RB1-74



LTE B7 15MHz 16QAM Middle Channel RB1-74



LTE B7 15MHz QPSK Middle Channel RB75-0



LTE B7 15MHz 16QAM Middle Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 15MHz QPSK High Channel RB1-0



LTE B7 15MHz 16QAM High Channel RB1-0



LTE B7 15MHz QPSK High Channel RB1-74



LTE B7 15MHz 16QAM High Channel RB1-74



LTE B7 15MHz QPSK High Channel RB75-0



LTE B7 15MHz 16QAM High Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 20MHz QPSK Low Channel RB1-0



LTE B7 20MHz 16QAM Low Channel RB1-0



LTE B7 20MHz QPSK Low Channel RB1-99



LTE B7 20MHz 16QAM Low Channel RB1-99



LTE B7 20MHz QPSK Low Channel RB100-0



LTE B7 20MHz 16QAM Low Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 20MHz QPSK Middle Channel RB1-0



LTE B7 20MHz 16QAM Middle Channel RB1-0



LTE B7 20MHz QPSK Middle Channel RB1-99



LTE B7 20MHz 16QAM Middle Channel RB1-99



LTE B7 20MHz QPSK Middle Channel RB100-0



LTE B7 20MHz 16QAM Middle Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B7 20MHz QPSK High Channel RB1-0



LTE B7 20MHz 16QAM High Channel RB1-0



LTE B7 20MHz QPSK High Channel RB1-99



LTE B7 20MHz 16QAM High Channel RB1-99



LTE B7 20MHz QPSK High Channel RB100-0



LTE B7 20MHz 16QAM High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.4. LTE BAND 12 BANDEDGE



LTE B12 1.4MHz QPSK Low Channel RB1-0



LTE B12 1.4MHz QPSK High Channel RB1-5



LTE B12 1.4MHz QPSK Low Channel RB6-0



LTE B12 1.4MHz QPSK High Channel RB6-0



LTE B12 1.4MHz 16QAM Low Channel RB1-0



LTE B12 1.4MHz 16QAM High Channel RB1-5

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 1.4MHz 16QAM Low Channel RB6-0



LTE B12 1.4MHz 16QAM High Channel RB6-0



LTE B12 3MHz QPSK Low Channel RB1-0



LTE B12 3MHz QPSK High Channel RB1-14



LTE B12 3MHz QPSK Low Channel RB15-0



LTE B12 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 3MHz 16QAM Low Channel RB1-0



LTE B12 3MHz 16QAM High Channel RB1-14



LTE B12 3MHz 16QAM Low Channel RB15-0



LTE B12 3MHz 16QAM High Channel RB15-0



LTE B12 5MHz QPSK Low Channel RB1-0



LTE B12 5MHz QPSK High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 5MHz QPSK Low Channel RB25-0



LTE B12 5MHz QPSK High Channel RB25-0



LTE B12 5MHz 16QAM Low Channel RB1-0



LTE B12 5MHz 16QAM High Channel RB1-24



LTE B12 5MHz 16QAM Low Channel RB25-0



LTE B12 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 10MHz QPSK Low Channel RB1-0



LTE B12 10MHz QPSK High Channel RB1-49



LTE B12 10MHz QPSK Low Channel RB50-0



LTE B12 10MHz QPSK High Channel RB50-0



LTE B12 10MHz 16QAM Low Channel RB1-0



LTE B12 10MHz 16QAM High Channel RB1-49

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B12 10MHz 16QAM Low Channel RB50-0



LTE B12 10MHz 16QAM High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.5. LTE BAND 13 ADJACENT CHANNEL POWER



LTE B13 5MHz QPSK Low Channel RB1-0



LTE B13 5MHz QPSK High Channel RB1-24



LTE B13 5MHz QPSK Low Channel RB25-0



LTE B13 5MHz QPSK High Channel RB25-0



LTE B13 5MHz 16QAM Low Channel RB1-0



LTE B13 5MHz 16QAM High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B13 5MHz 16QAM Low Channel RB25-0



LTE B13 5MHz 16QAM High Channel RB25-0



LTE B13 10MHz QPSK Middle Channel RB1-0



LTE B13 10MHz 16QAM Middle Channel RB1-0



LTE B13 10MHz QPSK Middle Channel RB1-49



LTE B13 10MHz 16QAM Middle Channel RB1-49

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B13 10MHz QPSK Middle Channel RB50-0



LTE B13 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.6. LTE BAND 17 BANDEDGE



LTE B17 5MHz QPSK Low Channel RB1-0



LTE B17 5MHz QPSK High Channel RB1-24



LTE B17 5MHz QPSK Low Channel RB25-0



LTE B17 5MHz QPSK High Channel RB25-0



LTE B17 5MHz 16QAM Low Channel RB1-0



LTE B17 5MHz 16QAM High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 5MHz 16QAM Low Channel RB25-0



LTE B17 5MHz 16QAM High Channel RB25-0



LTE B17 10MHz QPSK Low Channel RB1-0



LTE B17 10MHz QPSK High Channel RB1-49



LTE B17 10MHz QPSK Low Channel RB50-0



LTE B17 10MHz QPSK High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B17 10MHz 16QAM Low Channel RB1-0



LTE B17 10MHz 16QAM High Channel RB1-49



LTE B17 10MHz 16QAM Low Channel RB50-0



LTE B17 10MHz 16QAM High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.7. LTE BAND 25 BANDEDGE



LTE B25 1.4MHz QPSK Low Channel RB1-0



LTE B25 1.4MHz QPSK High Channel RB1-5



LTE B25 1.4MHz QPSK Low Channel RB6-0



LTE B25 1.4MHz QPSK High Channel RB6-0



LTE B25 1.4MHz 16QAM Low Channel RB1-0



LTE B25 1.4MHz 16QAM High Channel RB1-5

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 1.4MHz 16QAM Low Channel RB6-0



LTE B25 1.4MHz 16QAM High Channel RB6-0

LTE B25 3MHz QPSK Low Channel RB1-0



LTE B25 3MHz QPSK High Channel RB1-14



LTE B25 3MHz QPSK Low Channel RB15-0



LTE B25 3MHz QPSK High Channel RB15-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 3MHz 16QAM Low Channel RB1-0



LTE B25 3MHz 16QAM High Channel RB1-14



LTE B25 3MHz 16QAM Low Channel RB15-0



LTE B25 3MHz 16QAM High Channel RB15-0



LTE B25 5MHz QPSK Low Channel RB1-0



LTE B25 5MHz QPSK High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 5MHz QPSK Low Channel RB25-0



LTE B25 5MHz QPSK High Channel RB25-0



LTE B25 5MHz 16QAM Low Channel RB1-0



LTE B25 5MHz 16QAM High Channel RB1-24



LTE B25 5MHz 16QAM Low Channel RB25-0



LTE B25 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz QPSK Low Channel RB1-0



LTE B25 10MHz QPSK High Channel RB1-49



LTE B25 10MHz QPSK Low Channel RB50-0



LTE B25 10MHz QPSK High Channel RB50-0



LTE B25 10MHz 16QAM Low Channel RB1-0



LTE B25 10MHz 16QAM High Channel RB1-49

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 10MHz 16QAM Low Channel RB50-0



LTE B25 10MHz 16QAM High Channel RB50-0



LTE B25 15MHz QPSK Low Channel RB1-0



LTE B25 15MHz QPSK High Channel RB1-74



LTE B25 15MHz QPSK Low Channel RB75-0



LTE B25 15MHz QPSK High Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 15MHz 16QAM Low Channel RB1-0



LTE B25 15MHz 16QAM High Channel RB1-74



LTE B25 15MHz 16QAM Low Channel RB75-0



LTE B25 15MHz 16QAM High Channel RB75-0



LTE B25 20MHz QPSK Low Channel RB1-0



LTE B25 20MHz QPSK High Channel RB1-99

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B25 20MHz QPSK Low Channel RB100-0



LTE B25 20MHz QPSK High Channel RB100-0



LTE B25 20MHz 16QAM Low Channel RB1-0



LTE B25 20MHz 16QAM High Channel RB1-99



LTE B25 20MHz 16QAM Low Channel RB100-0



LTE B25 20MHz 16QAM High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.8. LTE BAND 26 EMISSION MASK (PART 90S)



LTE B26 1.4MHz QPSK Low Channel RB1-0 ID:12491



LTE B26 1.4MHz QPSK High Channel RB1-5 ID:12491



LTE B26 1.4MHz QPSK Low Channel RB6-0 ID:12491



LTE B26 1.4MHz QPSK High Channel RB6-0 ID:12491



LTE B26 1.4MHz 16QAM Low Channel RB1-0 ID:12491



LTE B26 1.4MHz 16QAM High Channel RB1-5 ID:12491

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 1.4MHz 16QAM Low Channel RB6-0 ID:12491



LTE B26 1.4MHz 16QAM High Channel RB6-0 ID:12491



LTE B26 3MHz QPSK Low Channel RB1-0 ID:12491

LTE B26 3MHz QPSK High Channel RB1-14 ID:12491



LTE B26 3MHz QPSK Low Channel RB15-0 ID:12491

LTE B26 3MHz QPSK High Channel RB15-0 ID:12491

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 3MHz 16QAM Low Channel RB1-0 ID:12491



LTE B26 3MHz 16QAM High Channel RB1-14 ID:12491



LTE B26 3MHz 16QAM Low Channel RB15-0 ID:12491

LTE B26 3MHz 16QAM High Channel RB15-0 ID:12491



LTE B26 5MHz QPSK Low Channel RB1-0 ID:12491



LTE B26 5MHz QPSK High Channel RB1-24 ID:12491

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

LTE B26 5MHz QPSK Low Channel RB25-0 ID:12491

LTE B26 5MHz QPSK High Channel RB25-0 ID:12491



LTE B26 5MHz 16QAM Low Channel RB1-0 ID:12491



LTE B26 5MHz 16QAM High Channel RB1-24 ID:12491

LTE B26 5MHz 16QAM Low Channel RB25-0 ID:12491

LTE B26 5MHz 16QAM High Channel RB25-0 ID:12491

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B26 10MHz QPSK Middle Channel RB1-0 ID:12491



LTE B26 10MHz 16QAM Middle Channel RB1-0 ID:12491

LTE B26 10MHz QPSK Middle Channel RB1-49 ID:12491



LTE B26 10MHz 16QAM Middle Channel RB1-49 ID:12491



LTE B26 10MHz QPSK Middle Channel RB50-0 ID:12491



LTE B26 10MHz 16QAM Middle Channel RB50-0 ID:12491

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.9. LTE BAND 30 ADJACENT CHANNEL POWER



LTE B30 5MHz QPSK Low Channel RB1-0



LTE B30 5MHz QPSK High Channel RB1-24



LTE B30 5MHz QPSK Low Channel RB25-0



LTE B30 5MHz QPSK High Channel RB25-0



LTE B30 5MHz 16QAM Low Channel RB1-0



LTE B30 5MHz 16QAM High Channel RB1-24

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 5MHz 16QAM Low Channel RB25-0



LTE B30 5MHz 16QAM High Channel RB25-0



LTE B30 10MHz QPSK Middle Channel RB1-0



LTE B30 10MHz 16QAM Middle Channel RB1-0



LTE B30 10MHz QPSK Middle Channel RB1-49



LTE B30 10MHz 16QAM Middle Channel RB1-49

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B30 10MHz QPSK Middle Channel RB50-0



LTE B30 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.10. LTE BAND 41 ADJACENT CHANNEL POWER



LTE B41 5MHz QPSK Low Channel RB1-0



LTE B41 5MHz 16QAM Low Channel RB1-0



LTE B41 5MHz QPSK Low Channel RB1-24



LTE B41 5MHz 16QAM Low Channel RB1-24



LTE B41 5MHz QPSK Low Channel RB25-0



LTE B41 5MHz 16QAM Low Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 5MHz QPSK Middle Channel RB1-0



LTE B41 5MHz 16QAM Middle Channel RB1-0



LTE B41 5MHz QPSK Middle Channel RB1-24



LTE B41 5MHz 16QAM Middle Channel RB1-24



LTE B41 5MHz QPSK Middle Channel RB25-0



LTE B41 5MHz 16QAM Middle Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 5MHz QPSK High Channel RB1-0



LTE B41 5MHz 16QAM High Channel RB1-0



LTE B41 5MHz QPSK High Channel RB1-24



LTE B41 5MHz 16QAM High Channel RB1-24



LTE B41 5MHz QPSK High Channel RB25-0



LTE B41 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK Low Channel RB1-0



LTE B41 10MHz 16QAM Low Channel RB1-0



LTE B41 10MHz QPSK Low Channel RB1-49



LTE B41 10MHz 16QAM Low Channel RB1-49



LTE B41 10MHz QPSK Low Channel RB50-0



LTE B41 10MHz 16QAM Low Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK Middle Channel RB1-0



LTE B41 10MHz 16QAM Middle Channel RB1-0



LTE B41 10MHz QPSK Middle Channel RB1-49



LTE B41 10MHz 16QAM Middle Channel RB1-49



LTE B41 10MHz QPSK Middle Channel RB50-0



LTE B41 10MHz 16QAM Middle Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 10MHz QPSK High Channel RB1-0



LTE B41 10MHz 16QAM High Channel RB1-0



LTE B41 10MHz QPSK High Channel RB1-49



LTE B41 10MHz 16QAM High Channel RB1-49



LTE B41 10MHz QPSK High Channel RB50-0



LTE B41 10MHz 16QAM High Channel RB50-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK Low Channel RB1-0



LTE B41 15MHz 16QAM Low Channel RB1-0



LTE B41 15MHz QPSK Low Channel RB1-74



LTE B41 15MHz 16QAM Low Channel RB1-74



LTE B41 15MHz QPSK Low Channel RB75-0



LTE B41 15MHz 16QAM Low Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK Middle Channel RB1-0



LTE B41 15MHz 16QAM Middle Channel RB1-0



LTE B41 15MHz QPSK Middle Channel RB1-74



LTE B41 15MHz 16QAM Middle Channel RB1-74



LTE B41 15MHz QPSK Middle Channel RB75-0



LTE B41 15MHz 16QAM Middle Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 15MHz QPSK High Channel RB1-0



LTE B41 15MHz 16QAM High Channel RB1-0



LTE B41 15MHz QPSK High Channel RB1-74



LTE B41 15MHz 16QAM High Channel RB1-74



LTE B41 15MHz QPSK High Channel RB75-0



LTE B41 15MHz 16QAM High Channel RB75-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 20MHz QPSK Low Channel RB1-0



LTE B41 20MHz 16QAM Low Channel RB1-0



LTE B41 20MHz QPSK Low Channel RB1-99



LTE B41 20MHz 16QAM Low Channel RB1-99



LTE B41 20MHz QPSK Low Channel RB100-0



LTE B41 20MHz 16QAM Low Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 20MHz QPSK Middle Channel RB1-0



LTE B41 20MHz 16QAM Middle Channel RB1-0



LTE B41 20MHz QPSK Middle Channel RB1-99



LTE B41 20MHz 16QAM Middle Channel RB1-99



LTE B41 20MHz QPSK Middle Channel RB100-0



LTE B41 20MHz 16QAM Middle Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B41 20MHz QPSK High Channel RB1-0



LTE B41 20MHz 16QAM High Channel RB1-0



LTE B41 20MHz QPSK High Channel RB1-99



LTE B41 20MHz 16QAM High Channel RB1-99



LTE B41 20MHz QPSK High Channel RB100-0



LTE B41 20MHz 16QAM High Channel RB100-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

8.2.11. LTE BAND 48 ADJACENT CHANNEL POWER



LTE B48 5MHz QPSK Low Channel RB1-0



LTE B48 5MHz 16QAM Low Channel RB1-0



LTE B48 5MHz QPSK Low Channel RB1-24



LTE B48 5MHz 16QAM Low Channel RB1-24



LTE B48 5MHz QPSK Low Channel RB25-0



LTE B48 5MHz 16QAM Low Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 5MHz QPSK Middle Channel RB1-0



LTE B48 5MHz 16QAM MiddleChannel RB1-0



LTE B48 5MHz QPSK MiddleChannel RB1-24



LTE B48 5MHz 16QAM MiddleChannel RB1-24



LTE B48 5MHz QPSK MiddleChannel RB25-0



LTE B48 5MHz 16QAM MiddleChannel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



LTE B48 5MHz QPSK High Channel RB1-0



LTE B48 5MHz 16QAM High Channel RB1-0



LTE B48 5MHz QPSK High Channel RB1-24



LTE B48 5MHz 16QAM High Channel RB1-24



LTE B48 5MHz QPSK High Channel RB25-0



LTE B48 5MHz 16QAM High Channel RB25-0

UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.