## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0




LOW CHANNEL 5955




MID CHANNEL 6175




HIGH CHANNEL 6415

## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 4




LOW CHANNEL 5955




MID CHANNEL 6175



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




**HIGH CHANNEL 6415**

## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 8

**LOW CHANNEL 5955**




**MID CHANNEL 6175**




**HIGH HANNEL6415**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 1TX Antenna 5 MODE (FCC) MOBILE – SU MODE




**LOW CHANNEL 5955**




**MID CHANNEL 6175**




**HIGH CHANNEL 6415**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0




LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175

MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415

HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 4

LOW CHANNEL ANT 6 5955

LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 8

LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – SU MODE




LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 0

LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 4

LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – 26-Tones, RU Index 8




LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 SDM MODE (FCC) – SU Mode




LOW CHANNEL ANT 6 5955




LOW CHANNEL ANT 5 5955




MID CHANNEL ANT 6 6175




MID CHANNEL ANT 5 6175




HIGH CHANNEL ANT 6 6415




HIGH CHANNEL ANT 5 6415



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 9.5.2. 802.11ax HE40 MODE IN THE UNII-5 BAND

**1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 0**

**LOW CHANNEL 5965**




**MID CHANNEL 6165**

**HIGH CHANNEL 6405**

**1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 8**




**LOW CHANNEL 5965**




**MID CHANNEL 6165**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




**HIGH CHANNEL 6405**

## 1TX Antenna 6 MODE (FCC) MOBILE – 26-Tones, RU Index 17




**LOW CHANNEL 5965**




**MID CHANNEL 6165**




**HIGH CHANNEL 6405**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 1TX Antenna 6 MODE (FCC) MOBILE – SU MODE




**LOW CHANNEL 5965**




**MID CHANNEL 6165**




**HIGH CHANNEL 6405**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 0




LOW CHANNEL 5965

MID CHANNEL 6165




HIGH CHANNEL 6405

## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 8

LOW CHANNEL 5965




MID CHANNEL 6165



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*




**HIGH CHANNEL 6405**

## 1TX Antenna 5 MODE (FCC) MOBILE – 26-Tones, RU Index 17




**LOW CHANNEL 5965**




**MID CHANNEL 6165**




**HIGH CHANNEL 6405**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 1TX Antenna 5 MODE (FCC) MOBILE – SU MODE




**LOW CHANNEL 5965**




**MID CHANNEL 6165**




**HIGH CHANNEL 6405**



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 0

LOW CHANNEL ANT 6 5965




LOW CHANNEL ANT 5 5965




MID CHANNEL ANT 6 6165




MID CHANNEL ANT 5 6165




HIGH CHANNEL ANT 6 6405




HIGH CHANNEL ANT 5 6405



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*

## 2TX Antenna 6 + Antenna 5 OFDMA MODE (FCC) – 26-Tones, RU Index 8




LOW CHANNEL ANT 6 5965

LOW CHANNEL ANT 5 5965




MID CHANNEL ANT 6 6165




MID CHANNEL ANT 5 6165




HIGH CHANNEL ANT 6 6405




HIGH CHANNEL ANT 5 6405



UL VERIFICATION SERVICES INC.
47173 Benicia Street, Fremont, CA 94538; USA TEL:(510) 319-4000 FAX:(510) 661-0888

*This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.*