

5G NR n41 40MHz BPSK Mid Channel RB1-0 Port A ID:27342



5G NR n41 40MHz BPSK Mid Channel RB1-105 Port A



5G NR n41 40MHz BPSK Mid Channel RB1-0 Port B ID:27342



5G NR n41 40MHz BPSK Mid Channel RB1-105 Port B



5G NR n41 40MHz BPSK Mid Channel RB1-0 Port A+B ID:27342



5G NR n41 40MHz BPSK Mid Channel RB1-105 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 40MHz BPSK High Channel RB1-0 Port A



5G NR n41 40MHz BPSK High Channel RB1-105 Port A



5G NR n41 40MHz BPSK High Channel RB1-0 Port B



5G NR n41 40MHz BPSK High Channel RB1-105 Port B



5G NR n41 40MHz BPSK High Channel RB1-0 Port A+B



5G NR n41 40MHz BPSK High Channel RB1-105 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 40MHz BPSK Low Channel RB100-0 Port A



5G NR n41 40MHz BPSK Mid Channel RB100-0 Port A
ID:27342



5G NR n41 40MHz BPSK Low Channel RB100-0 Port B



5G NR n41 40MHz BPSK Mid Channel RB100-0 Port B
ID:27342



5G NR n41 40MHz BPSK Low Channel RB100-0 Port A+B



5G NR n41 40MHz BPSK Mid Channel RB100-0 Port A+B
ID:27342

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000 FAX: (510) 661-0888
FORM NO: CCSUP4031B
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 40MHz BPSK High Channel RB100-0 Port A
ID:27342



5G NR n41 40MHz BPSK High Channel RB100-0 Port B
ID:27342



5G NR n41 40MHz BPSK High Channel RB100-0 Port A+B
ID:27342

Intentionally Blank

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK Low Channel RB1-0 Port A ID:27342



5G NR n41 50MHz BPSK Low Channel RB1-132 Port A



5G NR n41 50MHz BPSK Low Channel RB1-0 Port B ID:27342



5G NR n41 50MHz BPSK Low Channel RB1-132 Port B



5G NR n41 50MHz BPSK Low Channel RB1-0 Port A+B ID:27342



5G NR n41 50MHz BPSK Low Channel RB1-132 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK Middle Channel RB1-0 Port A



5G NR n41 50MHz BPSK Mid Channel RB1-132 Port A



5G NR n41 50MHz BPSK Middle Channel RB1-0 Port B



5G NR n41 50MHz BPSK Mid Channel RB1-132 Port B



5G NR n41 50MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n41 50MHz BPSK Mid Channel RB1-132 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK High Channel RB1-0 Port A



5G NR n41 50MHz BPSK High Channel RB1-132 Port A



5G NR n41 50MHz BPSK High Channel RB1-0 Port B



5G NR n41 50MHz BPSK High Channel RB1-132 Port B



5G NR n41 50MHz BPSK High Channel RB1-0 Port A+B



5G NR n41 50MHz BPSK High Channel RB1-132 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK Low Channel RB128-0 Port A
ID:27342



5G NR n41 50MHz BPSK Mid Channel RB128-0 Port A
ID:27342



5G NR n41 50MHz BPSK Low Channel RB128-0 Port B
ID:27342



5G NR n41 50MHz BPSK Mid Channel RB128-0 Port B
ID:27342



5G NR n41 50MHz BPSK Low Channel RB128-0 Port A+B
ID:27342



5G NR n41 50MHz BPSK Mid Channel RB128-0 Port A+B
ID:27342

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 50MHz BPSK High Channel RB128-0 Port A
ID:27342



5G NR n41 50MHz BPSK High Channel RB128-0 Port B
ID:27342



5G NR n41 50MHz BPSK High Channel RB128-0 Port A+B
ID:27342

Intentionally Blank

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK Low Channel RB1-0 Port A ID:27342



5G NR n41 60MHz BPSK Low Channel RB1-161 Port A



5G NR n41 60MHz BPSK Low Channel RB1-0 Port B ID:27342



5G NR n41 60MHz BPSK Low Channel RB1-161 Port B



5G NR n41 60MHz BPSK Low Channel RB1-0 Port A+B ID:27342



5G NR n41 60MHz BPSK Low Channel RB1-161 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000
FORM NO: CCSUP4031B
FAX: (510) 661-0888
This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK Middle Channel RB1-0 Port A



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port A



5G NR n41 60MHz BPSK Middle Channel RB1-0 Port B



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port B



5G NR n41 60MHz BPSK Middle Channel RB1-0 Port A+B



5G NR n41 60MHz BPSK Mid Channel RB1-161 Port A+B

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK High Channel RB1-0 Port A



5G NR n41 60MHz BPSK High Channel RB1-161 Port A



5G NR n41 60MHz BPSK High Channel RB1-0 Port B



5G NR n41 60MHz BPSK High Channel RB1-161 Port B



5G NR n41 60MHz BPSK High Channel RB1-0 Port A+B



5G NR n41 60MHz BPSK High Channel RB1-161 Port A+B

UL VERIFICATION SERVICES INC.
47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 319-4000

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.



5G NR n41 60MHz BPSK Low Channel RB162-0 Port A
ID:27342



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port A
ID:27342



5G NR n41 60MHz BPSK Low Channel RB162-0 Port B
ID:27342



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port B
ID:27342



5G NR n41 60MHz BPSK Low Channel RB162-0 Port A+B
ID:27342



5G NR n41 60MHz BPSK Mid Channel RB162-0 Port A+B
ID:27342

This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.