APPENDIX G

: INTERNAL PHOTOGRAPHS


SAMXON
SAMXON
NYLON COAT


TSU16AL-LF
5568719MP027A002
D5681D506E
L1510SN
K MST V1.3


2 3 4 5 6 7 8 9
5.5m
KR 9085
KSA 3750
15XX/17XX/19XXN
0520


CAUTION
HIGH VOLTAGE
SMEW N870A-TA
FL5424A282E2343
LG Innotek Co., Ltd.
YPLM-M002A
REV:A
2004/07/21
94V-0
SAMXON
68uF 450v
For continued protection against
risk of fire, Replace only with same
type and rating of fuse.
QC
OK
Hi-pot
OK


SOLDER
SOLDER
NYLON COAT


ZD4
JP1
VCC1
L10
ZD3
ZD1
D3
GND1
L2
R1
D1
ZD2
D2
C1
C2
C30
C4
C24
C6
R28
R27
R26
C7
C5
C25
LD1
R29
U10
U8
6.000
U2
C29
R4
LD7
U6
C8
R34
R33
R30
R35
R36
C10
L6
J3
D8
GND
G1
VCC
BC17


2 3 4 5 6 7
5.5m
KR 9085
KSA 3750
MADE IN KOREA
MA-330-21-B
ITM Inc.
OI5512AGST71A
TP4
ZD6
ZD5
ZD7
R32
R31
U11


5.5m
KR
9086
KSA
9750
1級
Kamaki
NYLON COAT


2 3 4 5 6 7 8 9
5.5m
KR 9085
KSA 3750

NYLON COAT

LM150X08
(A5)(N3)
LG PHILIPS LCD
MADE IN CHINA
NYLON COAT