Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE20	
U-NII Band I	U-NII Band 2A
5180MHz	5320MHz
RU Configuration: 26/0	RU Configuration: 26/8
	
RU Configuration: 52/37	RU Configuration: 52/40
	
RU Configuration: 106/53	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE20	
U-NII Band 2C	
5500MHz	5700MHz
RU Configuration: 26/0	RU Configuration: 26/8
	
RU Configuration: 52/37	RU Configuration: 52/40
	
RU Configuration: 106/53	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE20	
U-NII Band III	
5745MHz	5825MHz
RU Configuration: 26/0	RU Configuration: 26/8
	
RU Configuration: 52/37	RU Configuration: 52/40
	
RU Configuration: 106/53	RU Configuration: 106/54
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE40	
U-NII Band I	U-NII Band 2A
5190MHz	5310MHz
RU Configuration: 242/61	RU Configuration: 242/62
	
Band 2C	
5510MHz	5670MHz
RU Configuration: 242/61	RU Configuration: 242/62
	
Band III	
5755MHz	5795MHz
RU Configuration: 242/61	RU Configuration: 242/62
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE80	
U-NII Band I	U-NII Band 2A
5210MHz	5290MHz
RU Configuration: 484/65	RU Configuration: 484/65
	
Band 2C	
5530MHz	5610MHz
RU Configuration: 484/65	RU Configuration: 484/66
	
Band III	
5775MHz	
RU Configuration: 484/65	RU Configuration: 484/66
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Mode: 802.11ax-HE160	
U-NII Band I/2A	U-NII Band 2C
5250MHz	5570MHz
RU Configuration: 996/67	RU Configuration: 996/67
	
RU Configuration: 996/S67	RU Configuration: 996/S67
	

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City244, Taiwan
Tel: +886 2 26099301
Fax: +886 2 26099303

A.6 FREQUENCY STABILITY

Test Date	2022/01/05	Temp./Hum.	22℃/68%
Cable Loss	---	Tested By	Kuper Hsu
Test Voltage	AC 120V 60Hz (Via AC Adapter)		

A.6.1 Frequency stability Result

Temperature (℃)	Voltage (Vac)	Centre Frequency (MHz)	Measurement Value (MHz)	Frequency Stability (ppm)
25	120	5180	5180.004	0.772
-30	102		5179.972	-5.405
	138		5179.994	-1.158
-20	102		5179.993	-1.351
	138		5179.973	-5.212
-10	102		5179.98	-3.861
	138		5180.008	1.544
0	102		5179.976	-4.633
	138		5180.005	0.965
10	102		5179.985	-2.896
	138		5180.007	1.351
20	102		5179.975	-4.826
	138		5179.994	-1.158
30	102		5179.988	-2.317
	138		5179.974	-5.019
40	102		5179.975	-4.826
	138		5180.001	0.193
50	102		5179.971	-5.598
	138		5179.977	-4.440

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.