ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901174
Mode : Charging



Ctrl. No.: N/A

Report No.: 9901174
Mode: Charging

Tested By:Hong, Report No.:9901174
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
7.22500	29.7	48.0

* limit exceeded

Ctrl. No.: N/A

ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901174
Mode: Standby



Ctrl. No.: N/A

Report No.: 9901174
Mode : Standby

Tested By:Hong, Report No.:9901174
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
7.22500	30.8	48.0
10.84000	26.6	48.0

' limit exceeded

Ctrl. No.: N/A

ITS Intertek Testing Services
ETL Testing Laboratories

Report No.: 9901174
Mode: Transmission



Ctrl. No.: N/A

Report No.: 9901174
Mode : Transmission

Tested By:Hong, Report No.:9901174
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
7.22500	31.9	48.0
10.84000	27.5	48.0

* limit exceeded

Ctrl. No.: N/A