Before the WIFI subsystem is permanently disabled, called Force 7 80dB, the router software interface is as below. We can see the router has the column of wireless and supports WiFi.



This router also has another software version that does not support WIFI and it was checked by spectrum analyzer to ensure that there is no WIFI RF signal output. This software version interface is below; we can see the column of wireless disappears. We call this Force 5 industrial 2.0 booster.



48346 Milmont Drive Fremont, CA 94538 Phone: 510-770-0469 Fax: 510-996-7250
www.cellphone-mate.com

Both the 2 software versions are strictly controlled only in our factory to avoid other people to obtain them. And Force 5 industrial 2.0 before sending to customers, we will check each router software version, to ensure that does not support WIFI.

48346 Milmont Drive Fremont, CA 94538 Phone: 510-770-0469 Fax: 510-996-7250
www.cellphone-mate.com