

External photographs of equipment under test



Magnetic Mount in place



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 ExtPho

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 1 of 4

Back Magnetic Mount removed



Inside Battery cover



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 ExtPho

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 2 of 4

Sides



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 ExtPho

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 ExtPho

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 4 of 4