


Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 TSup

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 TSup

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 2 of 4



Rogers Labs, Inc.
 4405 West 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

FireBoard Labs LLC
 HVIN: FBRFS23
 Test: 230818
 Test to: CFR47 15C, RSS-210, RSS-247
 File: FBRFS23 TSup

FCC ID: 2A29A-FBRFS23
 IC: 27842-FBRFS23
 SN's: S432RZ64G, S6F32Z64G
 Date: November 14, 2023
 Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

FireBoard Labs LLC
HVIN: FBRFS23
Test: 230818
Test to: CFR47 15C, RSS-210, RSS-247
File: FBRFS23 TSup

FCC ID: 2A29A-FBRFS23
IC: 27842-FBRFS23
SN's: S432RZ64G, S6F32Z64G
Date: November 14, 2023
Page 4 of 4