

Declaration Letter of Model Difference

Date: 2026-10-08
FCC ID: 2A2J4-L1108
Tested Model Number: L1108
Adding Model Number(s): WP103, 863B, L863B, 863B-NFC, 1083D, WP32, L1208, 1083D-NFC, 1008, WP30, 763M, WP31, WP105, WP803, 1301, EP11, P308, 1108, L1008, P80, L871, L1083D, P15, 863L-NFC, S1401, WP95, 1101, 1083R, 763C, 1107, WP106, POE10, WP801, L1107, WP101, P105, 1108 NFC, 1102, OF3576S-8, 1163, L1401, 1037, L1083D-NFC, 2105, 1094, PT5010, 1032, TM140, F1150ZI-5, L1022IS, 1104, 1073, F716XM, 1019B, L1201D, 1040, 763B, 1105, 763, 863, 1150, 1108-NFC, smart vehicle infotainment, SH1, 763, 763KNX, L1301, WP80, 1083DD-NFC, WP20, 1038, 863A, N104, WL1895 NX, L1166IX, 1166, CP4-V88, 700, 1050, 863, 100, 400, 500, 600, 700, 800, 140, BF763A, 1091, PH55, 763, 863, 1063, 1071, F1030GR, 1083, 1410, F400, OF3576-11, 863L, P801-PoE, L870, WP70, L1030IS, GPS, G710, WL1863-4, 863C, 1063, H3576-32, S1201, 766, smart vehicle, F1150ZI-4, 1083P, H3576-21.5, 1007, NF400, WP102, OF3588S-8, 1093, L863L, 1019C, L1105, AP55A, OP110, 720, 1101IX, WP1095, 695, 702, L867P, 651G, F505P, 40P, F1560PM, P55M, 763/863/1063, PF1006, F763, 768B, L708XM-3D, F1071YI, AP55, 1401, F1063, 768, 1019, PH70/80, 1095, TOF, 707, 1098P, 1036, OF3576S-11, 619, 1260, W706XM, 1068, 768, 868, L1090EM, 1052, 1208, DC763C, DC863A, 1108Car, SoD3566-M, SoD3576-M, SoD3588S-M, H3576, H3588S, M3576S, M3562, BF763C, BF863A, BF863B, BF1008, BF1108

All Adding Model Number(s) is/are same electrically identical as Tested Model Number. It's just the difference in sales regions and models.

Yours Sincerely,

Applicant: Shenzhen Pretech Industrial Co., Ltd
Address: 808,8F,Qiancheng Commercial center,5 Haicheng Road,Bao' an District, Shenzhen, China
Contact Person: Daisy Ding
Tel.: +86-18086525816
Email: dd@pretech-e.com

Sincerely,

Signature: *Daisy ding*