

8 CONDUCTED RF OUTPUT POWER

8.2	WIFI Output Power
-----	-------------------

Note: When multiple channel bandwidth configurations in a frequency band have the same maximum turn-up output power, the test configuration is determined by applying the following steps sequentially:

- 1) The latest channel bandwidth configuration is selected among the multiple configurations in a frequency band with the same maximum turn-up output power.

WiFi6E Router on													
Mode	Channel	Frequency	All support										
			20MHz	20MHz	20MHz	20MHz	20MHz	20MHz	20MHz	20MHz	20MHz	20MHz	20MHz
11ax20	1	5200	3.21	3.43	3.69	4.32	4.50	7.50	Yes	Yes	Yes	Yes	
	3	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	5	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	7	5830	2.92	3.20	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	9	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	11	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	13	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	15	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	17	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	19	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax40	18	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	20	5410	2.98	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	22	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	24	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	26	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	28	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	30	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	32	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	34	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	36	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax80	37	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	39	5410	2.99	3.24	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	41	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	43	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	45	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	47	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	49	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	51	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	53	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	55	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax160	56	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	58	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	60	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	62	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	64	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	66	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	68	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	70	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	72	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	74	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax320	75	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	77	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	79	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	81	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	83	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	85	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	87	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	89	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	91	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	93	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax640	94	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	96	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	98	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	100	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	102	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	104	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	106	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	108	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	110	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	112	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax1280	113	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	115	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	117	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	119	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	121	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	123	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	125	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	127	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	129	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	131	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax2560	132	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	134	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	136	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	138	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	140	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	142	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	144	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	146	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	148	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	150	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax5120	151	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	153	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	155	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	157	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	159	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	161	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	163	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	165	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	167	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	169	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax10240	170	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	172	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	174	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	176	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	178	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	180	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	182	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	184	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	186	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	188	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax20480	189	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	191	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	193	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	195	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	197	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	199	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	201	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	203	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	205	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	207	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax40960	208	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	210	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	212	5620	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	214	5830	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	216	6040	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	218	6250	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	220	6460	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	222	6670	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	224	6880	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	226	7090	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
11ax81920	227	5200	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	229	5410	3.20	3.22	4.30	4.50	4.50	7.50	Yes	Yes	Yes	Yes	
	231												