




Appendix II

Setup Photographs


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)

PD336 Ant1


MEASUREMENT POSITION




MEASUREMENT POSITION (X axis)



MEASUREMENT POSITION (Y axis)




MEASUREMENT POSITION (Z axis)




PD336 Ant2
MEASUREMENT POSITION




MEASUREMENT POSITION (X axis)




MEASUREMENT POSITION (Y axis)




MEASUREMENT POSITION (Z axis)




PD513 Ant1
MEASUREMENT POSITION




MEASUREMENT POSITION (X axis)




MEASUREMENT POSITION (Y axis)




MEASUREMENT POSITION (Z axis)




PD513 Ant2
MEASUREMENT POSITION




MEASUREMENT POSITION (X axis)



MEASUREMENT POSITION (Y axis)




MEASUREMENT POSITION (Z axis)




RADIATED RF MEASUREMENT SETUP (30MHz~1GHz)


OS-PD336-PD



OSP-PD513-PD




OS-PD758-PD




RADIATED RF MEASUREMENT SETUP (Below 30MHz)


OS-PD336-PD



OSP-PD513-PD




OS-PD758-PD



RADIATED RF MEASUREMENT SETUP (AC Conducted Power Line)

OS-PD336-PD



OSP-PD513-PD



OS-PD758-PD

