





Appendix D: Band Edge

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dBm)	Verdict
Band66	1.4MHz	QPSK	131979	1RB#0	-23.55	PASS
Band66	1.4MHz	QPSK	131979	1RB#5	-49.89	PASS
Band66	1.4MHz	QPSK	131979	6RB#0	-30.56	PASS
Band66	1.4MHz	16QAM	131979	1RB#0	-24.55	PASS
Band66	1.4MHz	16QAM	131979	1RB#5	-50.86	PASS
Band66	1.4MHz	16QAM	131979	6RB#0	-31.58	PASS
Band66	1.4MHz	QPSK	132665	1RB#0	-51.04	PASS
Band66	1.4MHz	QPSK	132665	1RB#5	-22.12	PASS
Band66	1.4MHz	QPSK	132665	6RB#0	-27.35	PASS
Band66	1.4MHz	16QAM	132665	1RB#0	-52.49	PASS
Band66	1.4MHz	16QAM	132665	1RB#5	-25.32	PASS
Band66	1.4MHz	16QAM	132665	6RB#0	-29.81	PASS
Band66	3MHz	QPSK	131987	1RB#0	-19.37	PASS
Band66	3MHz	QPSK	131987	1RB#14	-44.04	PASS
Band66	3MHz	QPSK	131987	15RB#0	-29.85	PASS
Band66	3MHz	16QAM	131987	1RB#0	-20.39	PASS
Band66	3MHz	16QAM	131987	1RB#14	-44.73	PASS
Band66	3MHz	16QAM	131987	15RB#0	-31.21	PASS
Band66	3MHz	QPSK	132657	1RB#0	-43.97	PASS
Band66	3MHz	QPSK	132657	1RB#14	-19.91	PASS
Band66	3MHz	QPSK	132657	15RB#0	-28.33	PASS
Band66	3MHz	16QAM	132657	1RB#0	-44.77	PASS
Band66	3MHz	16QAM	132657	1RB#14	-21.12	PASS
Band66	3MHz	16QAM	132657	15RB#0	-29.62	PASS
Band66	5MHz	QPSK	131997	1RB#0	-16.63	PASS
Band66	5MHz	QPSK	131997	1RB#24	-51.75	PASS
Band66	5MHz	QPSK	131997	25RB#0	-29.85	PASS
Band66	5MHz	16QAM	131997	1RB#0	-17.86	PASS
Band66	5MHz	16QAM	131997	1RB#24	-52.18	PASS
Band66	5MHz	16QAM	131997	25RB#0	-32.10	PASS
Band66	5MHz	QPSK	132647	1RB#0	-51.49	PASS
Band66	5MHz	QPSK	132647	1RB#24	-16.83	PASS
Band66	5MHz	QPSK	132647	25RB#0	-28.79	PASS
Band66	5MHz	16QAM	132647	1RB#0	-52.15	PASS
Band66	5MHz	16QAM	132647	1RB#24	-19.04	PASS
Band66	5MHz	16QAM	132647	25RB#0	-30.30	PASS

Band66	10MHz	QPSK	132022	1RB#0	-16.82	PASS
Band66	10MHz	QPSK	132022	1RB#49	-47.93	PASS
Band66	10MHz	QPSK	132022	50RB#0	-30.71	PASS
Band66	10MHz	16QAM	132022	1RB#0	-17.39	PASS
Band66	10MHz	16QAM	132022	1RB#49	-48.39	PASS
Band66	10MHz	QPSK	132622	1RB#0	-47.50	PASS
Band66	10MHz	QPSK	132622	1RB#49	-16.92	PASS
Band66	10MHz	QPSK	132622	50RB#0	-30.35	PASS
Band66	10MHz	16QAM	132622	1RB#0	-47.57	PASS
Band66	10MHz	16QAM	132622	1RB#49	-17.80	PASS
Band66	15MHz	QPSK	132047	1RB#0	-17.76	PASS
Band66	15MHz	QPSK	132047	1RB#74	-46.77	PASS
Band66	15MHz	QPSK	132047	75RB#0	-31.75	PASS
Band66	15MHz	16QAM	132047	1RB#0	-18.65	PASS
Band66	15MHz	16QAM	132047	1RB#74	-47.36	PASS
Band66	15MHz	QPSK	132597	1RB#0	-46.63	PASS
Band66	15MHz	QPSK	132597	1RB#74	-17.38	PASS
Band66	15MHz	QPSK	132597	75RB#0	-30.13	PASS
Band66	15MHz	16QAM	132597	1RB#0	-46.68	PASS
Band66	15MHz	16QAM	132597	1RB#74	-18.20	PASS
Band66	20MHz	QPSK	132072	1RB#0	-19.87	PASS
Band66	20MHz	QPSK	132072	1RB#99	-44.36	PASS
Band66	20MHz	QPSK	132072	100RB#0	-34.09	PASS
Band66	20MHz	16QAM	132072	1RB#0	-20.82	PASS
Band66	20MHz	16QAM	132072	1RB#99	-46.13	PASS
Band66	20MHz	QPSK	132572	1RB#0	-43.85	PASS
Band66	20MHz	QPSK	132572	1RB#99	-19.72	PASS
Band66	20MHz	QPSK	132572	100RB#0	-32.39	PASS
Band66	20MHz	16QAM	132572	1RB#0	-44.27	PASS
Band66	20MHz	16QAM	132572	1RB#99	-21.11	PASS

Test Graphs



Waltek Testing Group (Shenzhen) Co., Ltd.

[Http://www.waltek.com.cn](http://www.waltek.com.cn)

