













Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	/
Band41_15MHz_QPSK_41165_1RB#0_20000~27000_20000~27000	/
/	
/	Band41_15MHz_16QAM_41165_1RB#0_30~1000_30~1000
	
Band41_15MHz_16QAM_41165_1RB#0_1000~20000_1000~20000	Band41_15MHz_16QAM_41165_1RB#0_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	
Band41_15MHz_QPSK_41165_1RB#74_30~1000_30~1000	Band41_15MHz_QPSK_41165_1RB#74_1000~20000_1000~20000
	/
Band41_15MHz_QPSK_41165_1RB#74_20000~27000_20000~27000	/
/	
/	Band41_15MHz_16QAM_41165_1RB#74_30~1000_30~1000





Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	/
Band41_20MHz_QPSK_40140_1RB#0_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_40140_1RB#0_30~1000_30~1000
	
Band41_20MHz_16QAM_40140_1RB#0_1000~20000_1000~20000	Band41_20MHz_16QAM_40140_1RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band41_20MHz_QPSK_40140_1RB#99_30~1000_30~1000	Band41_20MHz_QPSK_40140_1RB#99_1000~20000_1000~20000
	/
Band41_20MHz_QPSK_40140_1RB#99_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_40140_1RB#99_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	/
Band41_20MHz_QPSK_40590_1RB#0_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_40590_1RB#0_30~1000_30~1000
	
Band41_20MHz_16QAM_40590_1RB#0_1000~20000_1000~20000	Band41_20MHz_16QAM_40590_1RB#0_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	
Band41_20MHz_QPSK_40590_1RB#99_30~1000_30~1000	Band41_20MHz_QPSK_40590_1RB#99_1000~20000_1000~20000
	/
Band41_20MHz_QPSK_40590_1RB#99_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_40590_1RB#99_30~1000_30~1000





Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	/
Band41_20MHz_QPSK_41140_1RB#0_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_41140_1RB#0_30~1000_30~1000
	
Band41_20MHz_16QAM_41140_1RB#0_1000~20000_1000~20000	Band41_20MHz_16QAM_41140_1RB#0_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	
Band41_20MHz_QPSK_41140_1RB#99_30~1000_30~1000	Band41_20MHz_QPSK_41140_1RB#99_1000~20000_1000~20000
	/
Band41_20MHz_QPSK_41140_1RB#99_20000~27000_20000~27000	/
/	
/	Band41_20MHz_16QAM_41140_1RB#99_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Appendix F: Frequency Stability

Test Result

Voltage										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	VN	NT	780.00	0.307389	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	VL	NT	-1000.00	-0.394089	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	VH	NT	780.00	0.307389	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	VN	NT	1330.00	0.524138	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	VL	NT	1550.00	0.610837	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	VH	NT	560.00	0.220690	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	VN	NT	-5350.00	-2.065637	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	VL	NT	-470.00	-0.181467	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	VH	NT	-3370.00	-1.301158	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	VN	NT	1930.00	0.745174	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	VL	NT	290.00	0.111969	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	VH	NT	4160.00	1.606178	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	VN	NT	-2630.00	-0.991517	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	VL	NT	-1200.00	-0.452403	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	VH	NT	-1530.00	-0.576814	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	VN	NT	-4310.00	-1.624882	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	VL	NT	-4700.00	-1.771913	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	VH	NT	-4240.00	-1.598492	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	VN	NT	2360.00	0.929134	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	VL	NT	-220.00	-0.086614	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	VH	NT	-190.00	-0.074803	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	VN	NT	-6260.00	-2.464567	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	VL	NT	-5960.00	-2.346457	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	VH	NT	-3010.00	-1.185039	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	VN	NT	-770.00	-0.297297	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	VL	NT	-1320.00	-0.509653	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	VH	NT	-5150.00	-1.988417	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	VN	NT	1310.00	0.505792	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	VL	NT	3590.00	1.386100	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	VH	NT	4700.00	1.814672	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	VN	NT	-2550.00	-0.962264	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	VL	NT	-3000.00	-1.132075	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	VH	NT	-840.00	-0.316981	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	VN	NT	-3770.00	-1.422642	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	VL	NT	-5140.00	-1.939623	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	VH	NT	-6160.00	-2.324528	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	VN	NT	-160.00	-0.062930	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	VL	NT	-7870.00	-3.095379	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	VH	NT	-1410.00	-0.554572	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	VN	NT	-10470.00	-4.117994	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	VL	NT	-7970.00	-3.134710	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	VH	NT	-13590.00	-5.345133	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	VN	NT	5520.00	2.131274	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	VL	NT	10730.00	4.142857	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	VH	NT	2330.00	0.899614	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	VN	NT	-3280.00	-1.266409	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	VL	NT	-5400.00	-2.084942	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	VH	NT	-3440.00	-1.328185	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	VN	NT	-10510.00	-3.969783	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	VL	NT	-12930.00	-4.883853	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	VH	NT	-12880.00	-4.864967	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	VN	NT	-1220.00	-0.460812	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	VL	NT	-7590.00	-2.866856	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	VH	NT	-700.00	-0.264400	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	VN	NT	-12930.00	-5.080550	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	VL	NT	-8090.00	-3.178782	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	VH	NT	-15810.00	-6.212181	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	VN	NT	-18380.00	-7.222004	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	VL	NT	-13470.00	-5.292731	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	VH	NT	-16700.00	-6.561886	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	VN	NT	5900.00	2.277992	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	VL	NT	3570.00	1.378378	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	VH	NT	1980.00	0.764479	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	VN	NT	17560.00	6.779923	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	VL	NT	18030.00	6.961390	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	VH	NT	19030.00	7.347490	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	VN	NT	-7360.00	-2.782609	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	VL	NT	-10520.00	-3.977316	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	VH	NT	-6400.00	-2.419660	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	VN	NT	-7820.00	-2.956522	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	VL	NT	-5270.00	-1.992439	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	VH	NT	-17540.00	-6.631380	±NA	PASS

Temperature										
Band	Bandwidth	Modulation	Channel	RB Configure	Voltage [Vdc]	Temperature (°C)	Deviation (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	-30	-700.00	-0.275862	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	-20	-410.00	-0.161576	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	-10	350.00	0.137931	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	0	780.00	0.307389	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	10	600.00	0.236453	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	20	570.00	0.224631	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	30	2530.00	0.997044	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	40	830.00	0.327094	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40065	25RB#0	NV	50	2110.00	0.831527	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	-30	1670.00	0.658128	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	-20	2070.00	0.815764	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	-10	-140.00	-0.055172	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	0	460.00	0.181281	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	10	1060.00	0.417734	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	20	1910.00	0.752709	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	30	2280.00	0.898522	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	40	1010.00	0.398030	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40065	25RB#0	NV	50	2450.00	0.965517	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	-30	-4570.00	-1.764479	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	-20	-1890.00	-0.729730	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	-10	-4270.00	-1.648649	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	0	-1420.00	-0.548263	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	10	-6780.00	-2.617761	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	20	-3240.00	-1.250965	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	30	-2200.00	-0.849421	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	40	-4220.00	-1.629344	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	40590	25RB#0	NV	50	-2800.00	-1.081081	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	-30	3360.00	1.297297	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	-20	1560.00	0.602317	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	-10	3540.00	1.366795	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	0	3330.00	1.285714	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	10	1180.00	0.455598	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	20	3210.00	1.239382	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	30	3020.00	1.166023	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	40	1990.00	0.768340	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	40590	25RB#0	NV	50	1860.00	0.718147	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	-30	-1010.00	-0.380773	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	-20	-2130.00	-0.803016	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	-10	-710.00	-0.267672	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	0	-2010.00	-0.757776	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	10	-2350.00	-0.885957	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	20	-530.00	-0.199811	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	30	-1490.00	-0.561734	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	40	-2440.00	-0.919887	±NA	PASS
Band41(2535-2655)	5MHz	QPSK	41215	25RB#0	NV	50	-2260.00	-0.852026	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	-30	-3390.00	-1.278040	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	-20	-4010.00	-1.511781	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	-10	-4060.00	-1.530631	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	0	-4090.00	-1.541942	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	10	-3880.00	-1.462771	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	20	-3710.00	-1.398680	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	30	-3420.00	-1.289350	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	40	-4170.00	-1.572102	±NA	PASS
Band41(2535-2655)	5MHz	16QAM	41215	25RB#0	NV	50	-4810.00	-1.813384	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	-30	-80.00	-0.031496	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	-20	-2470.00	-0.972441	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	-10	130.00	0.051181	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	0	150.00	0.059055	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	10	-370.00	-0.145669	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	20	-970.00	-0.381890	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	30	730.00	0.287402	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	40	-1580.00	-0.622047	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40090	50RB#0	NV	50	400.00	0.157480	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	-30	-6360.00	-2.503937	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	-20	-4560.00	-1.795276	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	-10	-6100.00	-2.401575	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	0	-5840.00	-2.299213	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	10	-6180.00	-2.433071	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	20	-5460.00	-2.149606	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	30	-7030.00	-2.767717	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	40	-3530.00	-1.389764	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	10MHz	16QAM	40090	50RB#0	NV	50	-3580.00	-1.409449	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	-30	-1510.00	-0.583012	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	-20	-290.00	-0.111969	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	-10	-2980.00	-1.150579	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	0	-1830.00	-0.706564	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	10	-1790.00	-0.691120	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	20	-360.00	-0.138996	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	30	-2830.00	-1.092664	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	40	3100.00	1.196911	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	40590	50RB#0	NV	50	-4700.00	-1.814672	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	-30	5410.00	2.088803	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	-20	3990.00	1.540541	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	-10	3170.00	1.223938	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	0	1980.00	0.764479	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	10	4980.00	1.922780	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	20	1130.00	0.436293	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	30	1680.00	0.648649	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	40	2770.00	1.069498	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	40590	50RB#0	NV	50	3200.00	1.235521	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	-30	-2720.00	-1.026415	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	-20	-2230.00	-0.841509	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	-10	-5780.00	-2.181132	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	0	-4830.00	-1.822642	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	10	-1850.00	-0.698113	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	20	-4590.00	-1.732075	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	30	-4410.00	-1.664151	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	40	-1770.00	-0.667925	±NA	PASS
Band41(2535-2655)	10MHz	QPSK	41190	50RB#0	NV	50	-1910.00	-0.720755	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	-30	-4650.00	-1.754717	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	-20	-5090.00	-1.920755	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	-10	-3650.00	-1.377358	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	0	-4760.00	-1.796226	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	10	-6170.00	-2.328302	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	20	-4110.00	-1.550943	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	30	-4060.00	-1.532075	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	40	-5590.00	-2.109434	±NA	PASS
Band41(2535-2655)	10MHz	16QAM	41190	50RB#0	NV	50	-6750.00	-2.547170	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	-30	-3300.00	-1.297935	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	-20	-6370.00	-2.505408	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	-10	-3640.00	-1.431662	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	0	-2820.00	-1.109145	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	10	-2490.00	-0.979351	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	20	-3270.00	-1.286136	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	30	1040.00	0.409046	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	40	-5860.00	-2.304818	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40115	75RB#0	NV	50	-1590.00	-0.625369	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	-30	-9990.00	-3.929204	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	-20	-9160.00	-3.602753	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	-10	-16270.00	-6.399213	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	0	-12100.00	-4.759095	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	10	-10580.00	-4.161259	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	20	-12850.00	-5.054081	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	30	-14720.00	-5.789577	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	40	-11720.00	-4.609636	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40115	75RB#0	NV	50	-13330.00	-5.242871	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	-30	8490.00	3.277992	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	-20	5090.00	1.965251	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	-10	5870.00	2.266409	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	0	5350.00	2.065637	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	10	2360.00	0.911197	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	20	4990.00	1.926641	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	30	10470.00	4.042471	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	40	2840.00	1.096525	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	40590	75RB#0	NV	50	4320.00	1.667954	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	-30	-9550.00	-3.687259	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	-20	-8680.00	-3.351351	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	-10	-2540.00	-0.980695	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	0	-6210.00	-2.397683	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	10	-9710.00	-3.749035	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	20	-6640.00	-2.563707	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	30	-2800.00	-1.081081	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	40	-11230.00	-4.335907	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	40590	75RB#0	NV	50	-7950.00	-3.069498	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	-30	-8790.00	-3.320113	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	-20	-13020.00	-4.917847	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	-10	-3210.00	-1.212465	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	0	-7790.00	-2.942398	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	10	-7850.00	-2.965061	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	20	-9310.00	-3.516525	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	30	-9150.00	-3.456091	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	40	-12650.00	-4.778093	±NA	PASS
Band41(2535-2655)	15MHz	QPSK	41165	75RB#0	NV	50	-7050.00	-2.662890	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	-30	-3180.00	-1.201133	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	-20	-1170.00	-0.441926	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	-10	-6360.00	-2.402266	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	0	-7560.00	-2.855524	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	10	-460.00	-0.173749	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	20	-7170.00	-2.708215	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	30	1040.00	0.392823	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	40	-8890.00	-3.357885	±NA	PASS
Band41(2535-2655)	15MHz	16QAM	41165	75RB#0	NV	50	-3020.00	-1.140699	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	-30	-6660.00	-2.616896	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	-20	-22390.00	-8.797642	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	-10	-14670.00	-5.764244	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	0	-7790.00	-3.060904	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	10	-21900.00	-8.605108	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	20	-12510.00	-4.915521	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	30	-13340.00	-5.241650	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	40	-12060.00	-4.738703	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40140	100RB#0	NV	50	-12340.00	-4.848723	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	-30	-10940.00	-4.298625	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	-20	-16160.00	-6.349705	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	-10	-18690.00	-7.343811	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	0	-16970.00	-6.667976	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	10	-14970.00	-5.882122	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	20	-22240.00	-8.738703	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	30	-17780.00	-6.986248	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	40	-20320.00	-7.984283	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40140	100RB#0	NV	50	-14700.00	-5.776031	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	-30	5200.00	2.007722	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	-20	-1660.00	-0.640927	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	-10	-2840.00	-1.096525	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	0	-970.00	-0.374517	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	10	2300.00	0.888031	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	20	880.00	0.339768	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	30	-300.00	-0.115830	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	40	2010.00	0.776062	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	40590	100RB#0	NV	50	140.00	0.054054	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	-30	15080.00	5.822394	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	-20	21390.00	8.258687	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	-10	16690.00	6.444015	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	0	15840.00	6.115830	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	10	17130.00	6.613900	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	20	20000.00	7.722008	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	30	15190.00	5.864865	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	40	18160.00	7.011583	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	40590	100RB#0	NV	50	16640.00	6.424710	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	-30	-9100.00	-3.440454	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	-20	-5260.00	-1.988658	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	-10	-1450.00	-0.548204	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	0	-4570.00	-1.727788	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	10	-8900.00	-3.364839	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	20	-9750.00	-3.686200	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	30	-9840.00	-3.720227	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	40	-10920.00	-4.128544	±NA	PASS
Band41(2535-2655)	20MHz	QPSK	41140	100RB#0	NV	50	-3680.00	-1.391304	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	-30	-13540.00	-5.119093	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	-20	-11290.00	-4.268431	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	-10	-13170.00	-4.979206	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	0	-12560.00	-4.748582	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	10	-5880.00	-2.223062	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	20	-20520.00	-7.758034	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	30	-7200.00	-2.722117	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	40	-15100.00	-5.708885	±NA	PASS
Band41(2535-2655)	20MHz	16QAM	41140	100RB#0	NV	50	-8350.00	-3.156900	±NA	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.