

Shenyang Sanfeng Intelligent Technology Co., Ltd

Aug 09, 2022

Subject: Tuning and Adjustment of signal booster, FCC ID: 2A34B-SFZN003

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Hongmeng Zhao

A handwritten signature in black ink that reads "Hongmeng Zhao". The signature is written in a cursive, slightly slanted style.