







20007260
90000000
Rev. B1.2

D314
Out1 IR1

D322
Out2 IR1

X211
CAN

X210
CAN

X200

GND

D321
In3 IR1

TP302

Driving Direction -->

Switch divergent - 10

X370

- 12: CUFIS
- 11: CUFIS
- 10: Reserve
- 9: CUFIS
- 8: CUFIS
- 7: Hall sensor
- 6: IN1 IR3
- 5: IN1 IR2
- 4: GND
- 3: 45V
- 2: 45V
- 1: 45V

D313
In2 IR3

D312
In2 IR2

TOP


← Driving Direction


GLP-systems.com
20007260 A1.1
SwitchController 90 convergent
U_SMI_CON

D302
BUSY

D300
STATUS

D301
ERROR







REF 06R21-11
(12154 B)
(21) 0001519
(11) 201117
(240) 06R21-11
Alibaba