




Bottom

51/16

天津市东丽区方正测量工具制作中心 cm

GLPSYSTEMS
GLP12203 A
20020619 B1.1
2019W33

GLP-systems.com
20020221
Spiral Switch Controller
U_SPSW
Gerber 02

G531-0001033 B1.1

+5V
GND
+24V

X100

← Driving Direction

Top

ERROR
STATUS
BUSY

+3.3V

NXP
LPC1758FBD80
SC8846.1 03
ZSD1628A