









GLPSYSTEMS
GLP12154 A
20005591 B1.2
2019W44



<-- Driving Direction

GLP-systems.com
20007260 A1.1
SwitchController 90 convergent
U_SMI_CON

Driving Direction -->

X370
Switch divergent
Switch convergent - 10
12: C1F1S
11: C1F1S
10: Reserve
9: C1F1S
8: C1F1S
7: HallSensor
6: IN1 IQ3
5: IN1 IQ2
4: GND
3: GND
2: +5V
1: +5V

D301 ERROR
D300 STATUS
D302 BUSY

D313
In2 IQ3
D312
In2 IQ2

D321
In3 IQ1
TP302