


Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ac80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ax20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48




26dB BW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ax80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_8

26dB BW 802.11a
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11n20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48




26dB BW 802.11n40

Channel: 38



Channel: 46




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ac20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ac80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ax20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03

26dB BW 802.11ax80

Channel: 42




Report No.: AAEMT/EMC/220321-06-03


Test plots as followed: 5GHz_1

6dB BW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ax80

Channel: 155




Test plots as followed: 5GHz_2

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_3

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_4

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Date: 14, APR, 2022 07:32:20


Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_5

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_6

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_7

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ac80

Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_8

6dB BW 802.11a
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ac80


Channel: 155




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

6dB BW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


6dB BW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_1

99% OBW 802.11a
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03

Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03


Channel: 48



99% OBW 802.11n40
Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48




99% OBW 802.11ac40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03


99% OBW 802.11ax80
Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel:165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac40
Channel:151




Channel:159



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac80


Channel:155




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax20

Channel:149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


99% OBW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03

Test plots as followed: 5GHz_2

99% OBW 802.11a
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03


Channel: 48



99% OBW 802.11n20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n40

Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20
Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac40
Channel: 38




Channel: 46



Report No.: AAEMT/EMC/220321-06-03


99% OBW 802.11ac80
Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03


Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax80
Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11a
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03


Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20


Channel: 149



Channel: 157




Channel:165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac40

Channel:151




Channel:159



Report No.: AAEMT/EMC/220321-06-03


99% OBW 802.11ac80
Channel:155




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax20

Channel:149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax80
Channel: 155




Report No.: AAEMT/EMC/220321-06-03


Test plots as followed: 5GHz_3

99% OBW 802.11a

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03

Channel: 48



99% OBW 802.11n20

Channel: 36




Report No.: AAEMT/EMC/220321-06-03

Channel: 44




Channel: 48




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/220321-06-03

Channel: 48




99% OBW 802.11ac40

Channel: 38



Report No.: AAEMT/EMC/220321-06-03

Channel: 46



99% OBW 802.11ac80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48



99% OBW 802.11ax40

Channel: 38




Report No.: AAEMT/EMC/220321-06-03

Channel: 46



99% OBW 802.11ax80


Channel: 42




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11a

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/220321-06-03

Channel: 165




99% OBW 802.11n20

Channel: 149




Report No.: AAEMT/EMC/220321-06-03

Channel: 157




Channel: 165



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/220321-06-03

Channel: 165



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ac40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03


99% OBW 802.11ac80

Channel: 155




99% OBW 802.11ax20

Channel: 149




Report No.: AAEMT/EMC/220321-06-03

Channel: 157




Channel: 165




Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/220321-06-03

99% OBW 802.11ax80

Channel: 155




Report No.: AAEMT/EMC/220321-06-03


Test plots as followed: 5GHz_4

99% OBW 802.11a

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/220321-06-03

Channel: 48




99% OBW 802.11n20

Channel: 36



Date: 21.APR.2022 03:27:30


Channel: 44



Date: 21.APR.2022 03:27:52


Report No.: AAEMT/EMC/220321-06-03

Channel: 48



99% OBW 802.11n40

Channel: 38



Report No.: AAEMT/EMC/220321-06-03

Channel: 46



99% OBW 802.11ac20

Channel: 36

