





n40 5.230 GHz





Report No.: AAEMT/EMC/220321-06-03



ac20 5.180 GHz





ac20 5.240GHz





ac40 5.190GHz



ac40 5.230GHz





ac80 5.210GHz




Report No.: AAEMT/EMC/220321-06-03

ax20 5.180 GHz




Report No.: AAEMT/EMC/220321-06-03

ax20 5.240 GHz





Dates: 20.APR.2022 07:06:26





Dates: 20.APR.2022 07:11:26



ax40 5.190 GHz



ax40 5.230 GHz




ax80 5.210 GHz




Result plot as follows: 5GHz_5

a20 5.745 GHz





Date: 18.APR.2022 04:37:53





Date: 18.APR.2022 04:38:47



a20 5.825 GHz



n20 5.745 GHz




n20 5.825 GHz




Report No.: AAEMT/EMC/220321-06-03

n40 5.755 GHz





Date: 18.APR.2022 05:25:46





Date: 18.APR.2022 05:29:10



n40 5.795 GHz





ac20-5.745 GHz





ac20 5.825 GHz





ac40 5.755 GHz



ac40 5.795 GHz





ac80 5.775 GHz





Report No.: AAEMT/EMC/220321-06-03

ax20 5.745 GHz




Report No.: AAEMT/EMC/220321-06-03


ax20 5.825 GHz



ax40 5.755 GHz





Date: 18.APR.2022 05:26:51





Date: 18.APR.2022 05:27:36

ax40 5.795 GHz





ax80 5.775 GHz




Result plot as follows: 5GHz_6

a20 5.180 GHz




Report No.: AAEMT/EMC/220321-06-03

a20 5.240 GHz





Date: 20.APR.2022 04:35:12




Date: 20.APR.2022 04:39:11

n20 5.180 GHz




Report No.: AAEMT/EMC/220321-06-03

n20 5.240 GHz





Date: 20.APR.2022 04:39:09





Date: 20.APR.2022 04:44:42



n40 5.190 GHz





n40 5.230 GHz




ac20 5.180 GHz




ac20 5.240GHz



ac40 5.190GHz





Date: 20.APR.2022 05:15:51





Date: 20.APR.2022 05:21:39



ac40 5.230GHz





ac80 5.210GHz





ax20 5.180 GHz





ax20 5.240 GHz



ax40 5.190 GHz





ax40 5.230 GHz




Report No.: AAEMT/EMC/220321-06-03

ax80 5.210 GHz




Result plot as follows: 5GHz_6

a20 5.745 GHz





Date: 18.APR.2022 07:31:50





Date: 18.APR.2022 07:37:09

a20 5.825 GHz




Report No.: AAEMT/EMC/220321-06-03

n20 5.745 GHz




Report No.: AAEMT/EMC/220321-06-03

n20 5.825 GHz





Date: 18.APR.2022 07:56:14





Date: 18.APR.2022 07:46:07

n40 5.755 GHz





Report No.: AAEMT/EMC/220321-06-03



n40 5.795 GHz




ac20-5.745 GHz




ac20 5.825 GHz



ac40 5.755 GHz





Date: 18.APR.2022 09:06:57





Date: 18.APR.2022 09:09:39



ac40 5.795 GHz





ac80 5.775 GHz




ax20 5.745 GHz




ax20 5.825 GHz



ax40 5.755 GHz




Date: 18.APR.2022 08:07:49




Date: 18.APR.2022 08:12:00

ax40 5.795 GHz




Date: 18.APR.2022 08:08:15




Date: 18.APR.2022 08:12:46

ax80 5.775 GHz




Date: 18.APR.2022 08:31:09




Date: 18.APR.2022 08:32:23

Result plot as follows: 5GHz_7

a20 5.180 GHz





Date: 19, APR, 2022 09:23:36





Date: 19, APR, 2022 09:28:20



a20 5.240 GHz





n20 5.180 GHz




n20 5.240 GHz




n40 5.190 GHz



n40 5.230 GHz





Date: 19, APR, 2022 09:16:18





Date: 19, APR, 2022 09:19:29



ac20 5.180 GHz





ac20 5.240GHz





ac40 5.190GHz





ac40 5.230GHz





ac80 5.210GHz




ax20 5.180 GHz




ax20 5.240 GHz



ax40 5.190 GHz





Date: 19, APR, 2022 09:15:33




Date: 19, APR, 2022 09:17:42


ax40 5.230 GHz



ax80 5.210 GHz




Dates: 20.APR.2022 03:34:14




Dates: 20.APR.2022 03:35:15

Result plot as follows: 5GHz_7

a20 5.745 GHz




Date: 18.APR.2022 09:15:00




Date: 18.APR.2022 09:24:01

a20 5.825 GHz





Date: 18.APR.2022 09:20:15





Date: 18.APR.2022 09:25:13



n20 5.745 GHz





n20 5.825 GHz





n40 5.755 GHz




n40 5.795 GHz




ac20-5.745 GHz



ac20 5.825 GHz





Date: 18.APR.2022 09:21:30




Date: 18.APR.2022 09:27:16


ac40 5.755 GHz



ac40 5.795 GHz





Date: 18.APR.2022 09:56:48



Date: 18.APR.2022 09:57:21


Report No.: AAEMT/EMC/220321-06-03

ac80 5.775 GHz




Report No.: AAEMT/EMC/220321-06-03

ax20 5.745 GHz





Date: 18.APR.2022 09:21:46





Date: 18.APR.2022 09:27:43



ax20 5.825 GHz





ax40 5.755 GHz



ax40 5.795 GHz




ax80 5.775 GHz




Result plot as follows: 5GHz_8

a20 5.180 GHz





Date: 19, APR, 2022 07:19:58





Date: 19, APR, 2022 07:20:58

a20 5.240 GHz





Report No.: AAEMT/EMC/220321-06-03

n20 5.180 GHz




Report No.: AAEMT/EMC/220321-06-03


n20 5.240 GHz



n40 5.190 GHz





Date: 19, APR, 2022 07:49:02




Date: 19, APR, 2022 07:51:47


n40 5.230 GHz



ac20 5.180 GHz





Date: 19, APR, 2022 07:20:46





Date: 19, APR, 2022 07:24:52

Report No.: AAEMT/EMC/220321-06-03



ac20 5.240GHz



ac40 5.190GHz





ac40 5.230GHz





Report No.: AAEMT/EMC/220321-06-03

ac80 5.210GHz




ax20 5.180 GHz




Report No.: AAEMT/EMC/220321-06-03

ax20 5.240 GHz




Date: 19, APR, 2022 07:22:14




Date: 19, APR, 2022 07:27:04

ax40 5.190 GHz





Dates: 19, APR, 2022 07:48:12





Dates: 19, APR, 2022 07:50:55

ax40 5.230 GHz




ax80 5.210 GHz




Result plot as follows: 5GHz_8

a20 5.745 GHz





Date: 19, APR, 2022 09:01:12





Date: 19, APR, 2022 09:05:24

Report No.: AAEMT/EMC/220321-06-03


a20 5.825 GHz




n20 5.745 GHz



n20 5.825 GHz





Date: 19, APR, 2022 05:06:58




Date: 19, APR, 2022 05:12:56


n40 5.755 GHz



n40 5.795 GHz





Date: 19, APR, 2022 05:53:18





Date: 19, APR, 2022 05:56:48


ac20-5.745 GHz




ac20 5.825 GHz



ac40 5.755 GHz





Date: 19, APR, 2022 05:31:54





Date: 19, APR, 2022 05:33:55


ac40 5.795 GHz




ac80 5.775 GHz



ax20 5.745 GHz





Dates: 19, APR, 2022 09:02:36




Dates: 19, APR, 2022 09:07:36


ax20 5.825 GHz



ax40 5.755 GHz




Date: 19, APR, 2022 05:32:32




Date: 19, APR, 2022 05:35:25

ax40 5.795 GHz




Date: 19, APR, 2022 05:32:57




Date: 19, APR, 2022 05:35:52

Report No.: AAEMT/EMC/220321-06-03

ax80 5.775 GHz



Date: 19.APR.2022 06:46:43



Date: 19.APR.2022 06:41:49

11. ANTENNA REQUIREMENTS

11.1. Limit

15.203 requirement: For intentional device, according to 15.203: an intentional radiator shall be designed to ensure that no antenna other than that furnished by the responsible party shall be used with the device.

11.2. EUT ANTENNA

The antennas used for this product is Omni-directional that no antenna other than that furnished by the responsible party shall be used with the device, the maximum peak gain of the transmit antenna is 7dBi and the antenna connector is designed with detachable type antenna with N-type connector end and no consideration of replacement. Therefore the EUT is considered sufficient to comply with the provision.



.End of report****