

788CP



180° Angle Adjustment



360° Angle Adjustment

755CP



180° Angle Adjustment



Common problem

1. The FM transmitter has poor signal and noise interference.

Answer:

If the FM transmission signal is poor, you need to fix the car radio and plugin the antenna, and organize the wiring harness to avoid interference in the frequency band.

2. Wireless Carplay often disconnects or doesn't work.

Answer:

When connecting to carplay, do not connect the phone to other wireless networks to avoid carplay disconnection.

3. The bracket is not strong, the suction cup adhesion is not enough,
and the adhesion is unstable under high temperature.

Answer:

When sticking, pay attention to keep the sticky position clean and dry to avoid the occurrence of bubbles and unstable stickiness when sticking.

4. The bluetooth is out of sync, the caller can't hear the sound or there is noise.

Answer:

Make sure that the mic position is not blocked by foreign objects.

Wiring instructions



Product parameters

NAME	755CP
Wireless system	Apple Carplay,Android Auto
Screen	7 inch IPS material,1024*600 resolution
Wireless module	Wi-Fi,BT
Built-in speaker	2 w speaker
FM launch	Adjustable frequency 87MHz-108MHz
Reverse image	Automatic reversing video display
Working power range	12-24v
Working temperature	- 20°C-+ 70°C
Interface	USB/TF Card/avin/audio/CD

NAME	788CP
Wireless system	Apple Carplay,Android Auto
Screen	7 inch IPS material,1024*600 resolution
Wireless module	Wi-Fi,BT
Built-in speaker	2 w speaker
FM launch	Adjustable frequency 87MHz-108MHz
Reverse image	Automatic reversing video display
Working power range	12-24v
Working temperature	- 20°C-+ 70°C
Interface	USB/TF Card/avin/audio/CD

NAME	1026CP
Wireless system	Apple Carplay,Android Auto
Screen	10.26 inch IPS material, 1920*1080 resolution
Wireless module	Wi-Fi,BT
Built-in speaker	2 w speaker
FM launch	Adjustable frequency 87MHz-108MHz
Reverse image	Automatic reversing video display
Working power range	12-24v
Working temperature	- 20°C-+ 70°C
Interface	USB/TF Card/avin/audio/CD

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Warning: changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment

Radiation Exposure Statement

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment.

This equipment should be installed and operated with minimum distance 20cm between the radiator and your body.