


16. EUT Test Setup Photographs

Conducted Emissions Photo

Adapter Model: TPA-418G050100UU01



Adapter Model: YMK-10W050100



Adapter Model: QL010-0501000UU



Radiated Measurement Photos

Adapter Model: TPA-418G050100UU01



Adapter Model: YMK-10W050100



Adapter Model: QL010-0501000UU



