







11N40SISO_Ant1_5795




11AC20SISO_Ant1_5180




11AC20SISO_Ant1_5220




11AC20SISO_Ant1_5240




11AC20SISO_Ant1_5745




11AC20SISO_Ant1_5785




11AC20SISO_Ant1_5825



11AC40SISO_Ant1_5190




11AC40SISO_Ant1_5230




Date: 24.MAR.2022 11:46:12

11AC40SISO_Ant1_5755




Date: 24.MAR.2022 11:55:47

11AC40SISO_Ant1_5795



Date: 24.MAR.2022 14:39:41

11AC80SISO_Ant1_5210



-----End of the report-----