





11AC40SISO\_Ant1\_High\_5795



11AC80SISO\_Ant1\_Low\_5775

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



# TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397


E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

### 11A\_Ant2\_Low\_5180



### 11A\_Ant2\_High\_5240



### 11N20SISO\_Ant2\_Low\_5180

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_High\_5240



11N40SISO\_Ant2\_Low\_5190

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant2\_High\_5230



11AC20SISO\_Ant2\_Low\_5180

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_High\_5240



11AC40SISO\_Ant2\_Low\_5190

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_High\_5230



11AC80SISO\_Ant2\_Low\_5210

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397


E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

## 11A\_Ant2\_Low\_5745



## 11A\_Ant2\_High\_5825



## 11N20SISO\_Ant2\_Low\_5745


TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N20SISO\_Ant2\_High\_5825



11N40SISO\_Ant2\_Low\_5755

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant2\_High\_5795



11AC20SISO\_Ant2\_Low\_5745

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_High\_5825



11AC40SISO\_Ant2\_Low\_5755

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_High\_5795



11AC80SISO\_Ant2\_Low\_5775

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

## Appendix F: Conducted Spurious Emission

### Test Result

| TestMode  | Antenna | Frequency[MHz] | FreqRange [MHz] | Max. Fre [MHz] | Max. Level [dBm] | Limit [dBm] | Verdict |
|-----------|---------|----------------|-----------------|----------------|------------------|-------------|---------|
| 11A       | Ant1    | 5180           | 30~5140         | 5137.87        | -33.72           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39845.9        | -32.7            | ≤-27        | PASS    |
|           |         | 5220           | 30~5140         | 5029.71        | -35.71           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39815.8        | -32.29           | ≤-27        | PASS    |
|           |         | 5240           | 30~5140         | 2616.85        | -30              | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39132.3        | -31.97           | ≤-27        | PASS    |
|           |         | 5745           | 30~5650         | 5619.18        | -29.26           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39788.2        | -27.72           | ≤-27        | PASS    |
|           |         | 5785           | 30~5650         | 4493.72        | -29.92           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39202.1        | -28.31           | ≤-27        | PASS    |
|           |         | 5825           | 30~5650         | 5153.86        | -29.25           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39115.8        | -27.23           | ≤-27        | PASS    |
| 11N20SISO | Ant1    | 5180           | 30~5140         | 5139.4         | -33.24           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39820.5        | -32.57           | ≤-27        | PASS    |
|           |         | 5220           | 30~5140         | 5138.72        | -31.92           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39728.1        | -32.02           | ≤-27        | PASS    |
|           |         | 5240           | 30~5140         | 2460.83        | -34.16           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39535.3        | -32.21           | ≤-27        | PASS    |
|           |         | 5745           | 30~5650         | 5416.68        | -30.01           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39168          | -28.16           | ≤-27        | PASS    |
|           |         | 5785           | 30~5650         | 5363.3         | -29.63           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39816.6        | -28.22           | ≤-27        | PASS    |
|           |         | 5825           | 30~5650         | 5358.99        | -29.4            | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39231.6        | -28.22           | ≤-27        | PASS    |
| 11N40SISO | Ant1    | 5190           | 30~5140         | 5139.4         | -31.05           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 38820.5        | -33.15           | ≤-27        | PASS    |
|           |         | 5230           | 30~5140         | 5128.33        | -34.72           | ≤-27        | PASS    |
|           |         |                | 5360~40000      | 39133.5        | -32.4            | ≤-27        | PASS    |
|           |         | 5755           | 30~5650         | 5541.44        | -29.47           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39160.1        | -28.44           | ≤-27        | PASS    |
|           |         | 5795           | 30~5650         | 5448.16        | -29.74           | ≤-27        | PASS    |
|           |         |                | 5925~40000      | 39160.1        | -28.44           | ≤-27        | PASS    |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|            |      |      |            |         |        |      |      |
|------------|------|------|------------|---------|--------|------|------|
|            |      |      | 5925~40000 | 39254.4 | -28.14 | ≤-27 | PASS |
| 11AC20SISO | Ant1 | 5180 | 30~5140    | 38676.2 | -31.83 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39220   | -32.26 | ≤-27 | PASS |
|            |      | 5220 | 30~5140    | 5139.57 | -32.12 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39157.7 | -32.33 | ≤-27 | PASS |
|            |      | 5240 | 30~5140    | 5113.85 | -34.55 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39180.8 | -31.68 | ≤-27 | PASS |
|            |      | 5745 | 30~5650    | 5362.17 | -29.17 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39280.5 | -27.84 | ≤-27 | PASS |
|            |      | 5785 | 30~5650    | 5159.3  | -30.21 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39566.7 | -28.46 | ≤-27 | PASS |
| 11AC40SISO | Ant1 | 5190 | 30~5140    | 5139.06 | -33.31 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39830.8 | -32.83 | ≤-27 | PASS |
|            |      | 5230 | 30~5140    | 5109.09 | -35.01 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39212   | -32.5  | ≤-27 | PASS |
|            |      | 5755 | 30~5650    | 5079.87 | -29.71 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39873.4 | -28.13 | ≤-27 | PASS |
| 11AC80SISO | Ant1 | 5210 | 30~5140    | 5121.01 | -31.85 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39676.1 | -31.82 | ≤-27 | PASS |
|            |      | 5775 | 30~5650    | 5628.93 | -30.09 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39864.3 | -28.64 | ≤-27 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

| TestMode   | Antenna | Frequency[MHz] | FreqRange [MHz] | Max. Fre [MHz] | Max. Level [dBm] | Limit [dBm] | Verdict |
|------------|---------|----------------|-----------------|----------------|------------------|-------------|---------|
| 11A        | Ant2    | 5180           | 30~5140         | 3579.03        | -36.58           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39231.6        | -32.53           | ≤-27        | PASS    |
|            |         | 5220           | 30~5140         | 5039.59        | -35.87           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39233.9        | -31.56           | ≤-27        | PASS    |
|            |         | 5240           | 30~5140         | 4552.28        | -36.29           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39309          | -31.02           | ≤-27        | PASS    |
|            |         | 5745           | 30~5650         | 5587.34        | -29.31           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39134          | -28.14           | ≤-27        | PASS    |
|            |         | 5785           | 30~5650         | 5458.83        | -29.66           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39776.8        | -27.59           | ≤-27        | PASS    |
| 11N20SISO  | Ant2    | 5180           | 30~5140         | 4868.92        | -35.98           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39239.7        | -32.05           | ≤-27        | PASS    |
|            |         | 5220           | 30~5140         | 4925.81        | -35.47           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39733.9        | -31.15           | ≤-27        | PASS    |
|            |         | 5240           | 30~5140         | 5116.41        | -36.21           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39821.6        | -31.61           | ≤-27        | PASS    |
|            |         | 5745           | 30~5650         | 5298.48        | -29.79           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39147.6        | -27.7            | ≤-27        | PASS    |
|            |         | 5785           | 30~5650         | 4651.08        | -29.79           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39130.5        | -27.21           | ≤-27        | PASS    |
| 11N40SISO  | Ant2    | 5190           | 30~5140         | 4684.63        | -36.01           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39631.1        | -32.11           | ≤-27        | PASS    |
|            |         | 5230           | 30~5140         | 4069.24        | -36.01           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39195.8        | -32.21           | ≤-27        | PASS    |
|            |         | 5755           | 30~5650         | 5573.1         | -29.75           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39805.2        | -28.23           | ≤-27        | PASS    |
|            |         | 5795           | 30~5650         | 5166.04        | -29.04           | ≤-27        | PASS    |
|            |         |                | 5925~40000      | 39285          | -28.29           | ≤-27        | PASS    |
| 11AC20SISO | Ant2    | 5180           | 30~5140         | 4601.17        | -36.16           | ≤-27        | PASS    |
|            |         |                | 5360~40000      | 39649.6        | -32.19           | ≤-27        | PASS    |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|            |      |      |            |         |        |      |      |
|------------|------|------|------------|---------|--------|------|------|
|            |      | 5220 | 30~5140    | 4926.32 | -36.4  | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39793.9 | -31.34 | ≤-27 | PASS |
|            |      | 5240 | 30~5140    | 4921.73 | -36.13 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39594.1 | -31.88 | ≤-27 | PASS |
|            |      | 5745 | 30~5650    | 5275.44 | -29.73 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39760.9 | -28.74 | ≤-27 | PASS |
|            |      | 5785 | 30~5650    | 5340.07 | -29.69 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39643.9 | -27.74 | ≤-27 | PASS |
| 11AC40SISO | Ant2 | 5190 | 30~5140    | 4699.96 | -36.09 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39176.2 | -32.06 | ≤-27 | PASS |
|            |      | 5230 | 30~5140    | 4960.39 | -35.52 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39761.6 | -31.42 | ≤-27 | PASS |
|            |      | 5755 | 30~5650    | 5323.02 | -29.59 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39174.8 | -27.9  | ≤-27 | PASS |
|            |      | 5795 | 30~5650    | 3543.98 | -29.88 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39172.6 | -28.41 | ≤-27 | PASS |
| 11AC80SISO | Ant2 | 5210 | 30~5140    | 4827.87 | -35.68 | ≤-27 | PASS |
|            |      |      | 5360~40000 | 39102.3 | -31.43 | ≤-27 | PASS |
|            |      | 5775 | 30~5650    | 5647.1  | -30.11 | ≤-27 | PASS |
|            |      |      | 5925~40000 | 39922.2 | -27.95 | ≤-27 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

## Test Graphs



TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant1\_5220\_5360~40000



11A\_Ant1\_5240\_30~5140

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant1\_5240\_5360~40000



11A\_Ant1\_5745\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11A\_Ant1\_5745\_5925~40000



11A\_Ant1\_5785\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11A\_Ant1\_5785\_5925~40000



11A\_Ant1\_5825\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11A\_Ant1\_5825\_5925~40000



11N20SISO\_Ant1\_5180\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant1\_5180\_5360~40000



11N20SISO\_Ant1\_5220\_30~5140

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N20SISO\_Ant1\_5220\_5360~40000



11N20SISO\_Ant1\_5240\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant1\_5240\_5360~40000



11N20SISO\_Ant1\_5745\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N20SISO\_Ant1\_5745\_5925~40000



11N20SISO\_Ant1\_5785\_30~5650


# TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N20SISO\_Ant1\_5785\_5925~40000



11N20SISO\_Ant1\_5825\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985 2678


Fax: +(86) 0755-2985 2397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N20SISO\_Ant1\_5825\_5925~40000



11N40SISO\_Ant1\_5190\_30~5140

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant1\_5190\_5360~40000



11N40SISO\_Ant1\_5230\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N40SISO\_Ant1\_5230\_5360~40000



11N40SISO\_Ant1\_5755\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N40SISO\_Ant1\_5755\_5925~40000



11N40SISO\_Ant1\_5795\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11N40SISO\_Ant1\_5795\_5925~40000



11AC20SISO\_Ant1\_5180\_30~5140


# TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant1\_5180\_5360~40000



11AC20SISO\_Ant1\_5220\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11AC20SISO\_Ant1\_5220\_5360~40000



11AC20SISO\_Ant1\_5240\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11AC20SISO\_Ant1\_5240\_5360~40000



11AC20SISO\_Ant1\_5745\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985 2678


Fax: +(86) 0755-2985 2397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11AC20SISO\_Ant1\_5745\_5925~40000



11AC20SISO\_Ant1\_5785\_30~5650


# TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant1\_5785\_5925~40000



11AC20SISO\_Ant1\_5825\_30~5650


#### TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant1\_5825\_5925~40000



11AC40SISO\_Ant1\_5190\_30~5140

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11AC40SISO\_Ant1\_5190\_5360~40000



11AC40SISO\_Ant1\_5230\_30~5140

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678


Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



11AC40SISO\_Ant1\_5230\_5360~40000



11AC40SISO\_Ant1\_5755\_30~5650

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant1\_5755\_5925~40000



11AC40SISO\_Ant1\_5795\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant1\_5795\_5925~40000



11AC80SISO\_Ant1\_5210\_30~5140

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC80SISO\_Ant1\_5210\_5360~40000



11AC80SISO\_Ant1\_5775\_30~5650

#### TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678

Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park, Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-29852678

Fax: +(86) 0755-29852397

E-mail: info@gdksign.cn

Web: www.gdksign.com



TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant2\_5220\_5360~40000



11A\_Ant2\_5240\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant2\_5240\_5360~40000



11A\_Ant2\_5745\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant2\_5745\_5925~40000



11A\_Ant2\_5785\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant2\_5785\_5925~40000



11A\_Ant2\_5825\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11A\_Ant2\_5825\_5925~40000



11N20SISO\_Ant2\_5180\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5180\_5360~40000



11N20SISO\_Ant2\_5220\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5220\_5360~40000



11N20SISO\_Ant2\_5240\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5240\_5360~40000



11N20SISO\_Ant2\_5745\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5745\_5925~40000



11N20SISO\_Ant2\_5785\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5785\_5925~40000



11N20SISO\_Ant2\_5825\_30~5650

# TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N20SISO\_Ant2\_5825\_5925~40000



11N40SISO\_Ant2\_5190\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant2\_5190\_5360~40000



11N40SISO\_Ant2\_5230\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant1\_5230\_5360~40000



11N40SISO\_Ant2\_5755\_30~5650

#### TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant2\_5755\_5925~40000



11N40SISO\_Ant2\_5795\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11N40SISO\_Ant2\_5795\_5925~40000



11AC20SISO\_Ant2\_5180\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5180\_5360~40000



11AC20SISO\_Ant2\_5220\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5220\_5360~40000



11AC20SISO\_Ant2\_5240\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5240\_5360~40000



11AC20SISO\_Ant2\_5745\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5745\_5925~40000



11AC20SISO\_Ant2\_5785\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5785\_5925~40000



11AC20SISO\_Ant2\_5825\_30~5650


TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China


Tel: +(86) 0755-2985 2678 Fax: +(86) 0755-2985 2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC20SISO\_Ant2\_5825\_5925~40000



11AC40SISO\_Ant2\_5190\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_5190\_5360~40000



11AC40SISO\_Ant2\_5230\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_5230\_5360~40000



11AC40SISO\_Ant2\_5755\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_5755\_5925~40000



11AC40SISO\_Ant2\_5795\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC40SISO\_Ant2\_5795\_5925~40000



11AC80SISO\_Ant2\_5210\_30~5140

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678


Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



11AC80SISO\_Ant2\_5210\_5360~40000



11AC80SISO\_Ant2\_5775\_30~5650

TRF RF\_R1


Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com



TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

## Appendix G: Frequency Stability

### Test Result

| Voltage       |         |         |               |                  |                |                 |             |         |
|---------------|---------|---------|---------------|------------------|----------------|-----------------|-------------|---------|
| TestMode      | Antenna | Channel | Voltage [Vdc] | Temperature (°C) | Deviation (Hz) | Deviation (ppm) | Limit (ppm) | Verdict |
| 11A           | Ant1    | 5180    | NV            | NT               | 1000           | 0.19305         | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5200    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 1000           | 0.192308        | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5240    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5745    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 1000           | 0.174064        | 20          | PASS    |
|               |         |         | HV            | NT               | 1000           | 0.174064        | 20          | PASS    |
|               |         | 5785    | NV            | NT               | 1000           | 0.172861        | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5825    | NV            | NT               | 1000           | 0.171674        | 20          | PASS    |
|               |         |         | LV            | NT               | 1000           | 0.171674        | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
| 11N20SI<br>SO | Ant1    | 5180    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5200    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5240    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 1000           | 0.19084         | 20          | PASS    |
|               |         |         | HV            | NT               | 1000           | 0.19084         | 20          | PASS    |
|               |         | 5745    | NV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | LV            | NT               | 0              | 0               | 20          | PASS    |
|               |         |         | HV            | NT               | 0              | 0               | 20          | PASS    |
|               |         | 5785    | NV            | NT               | 0              | 0               | 20          | PASS    |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

|                |      |      |    |    |      |          |    |      |
|----------------|------|------|----|----|------|----------|----|------|
| 11N40SI<br>SO  | Ant1 | 5825 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5190 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5230 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 1000 | 0.173762 | 20 | PASS |
| 11AC20S<br>ISO | Ant1 | 5755 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5795 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5180 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5200 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5240 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5745 | LV | NT | 1000 | 0.174064 | 20 | PASS |
|                |      |      | HV | NT | 1000 | 0.174064 | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
| 11AC40S<br>ISO | Ant1 | 5785 | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
|                |      | 5825 | LV | NT | 1000 | 0.171674 | 20 | PASS |
|                |      |      | HV | NT | 1000 | 0.171674 | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |
| 11AC40S<br>ISO | Ant1 | 5190 | LV | NT | 1000 | 0.192678 | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      |      | NV | NT | 0    | 0        | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|                |      |      |    |    |      |          |    |      |
|----------------|------|------|----|----|------|----------|----|------|
|                |      | 5230 | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 1000 | 0.191205 | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      | 5755 | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 1000 | 0.173762 | 20 | PASS |
|                |      |      | HV | NT | 1000 | 0.173762 | 20 | PASS |
|                |      | 5795 | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 0    | 0        | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
| 11AC80S<br>ISO | Ant1 | 5210 | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 1000 | 0.191939 | 20 | PASS |
|                |      |      | HV | NT | 0    | 0        | 20 | PASS |
|                |      | 5775 | NV | NT | 0    | 0        | 20 | PASS |
|                |      |      | LV | NT | 1000 | 0.17316  | 20 | PASS |
|                |      |      | HV | NT | 1000 | 0.17316  | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

| Temperature |         |         |               |                  |                |                 |             |         |
|-------------|---------|---------|---------------|------------------|----------------|-----------------|-------------|---------|
| TestMode    | Antenna | Channel | Voltage [Vdc] | Temperature (°C) | Deviation (Hz) | Deviation (ppm) | Limit (ppm) | Verdict |
| 11A         | Ant1    | 5180    | NV            | -30              | 1000           | 0.19305         | 20          | PASS    |
|             |         |         | NV            | -20              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -10              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 0                | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 10               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 20               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 30               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 40               | 0              | 0               | 20          | PASS    |
|             |         | 5200    | NV            | 50               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -30              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -20              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -10              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 0                | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 10               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 20               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 30               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 40               | 0              | 0               | 20          | PASS    |
|             |         | 5240    | NV            | 50               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -30              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -20              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -10              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 0                | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 10               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 20               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 30               | 0              | 0               | 20          | PASS    |
|             |         | 5745    | NV            | 40               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 50               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -30              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -20              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | -10              | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 0                | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 10               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 20               | 0              | 0               | 20          | PASS    |
|             |         |         | NV            | 30               | 0              | 0               | 20          | PASS    |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|               |      |      |    |     |      |          |    |      |
|---------------|------|------|----|-----|------|----------|----|------|
|               |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0        | 20 | PASS |
|               |      | 5785 | NV | -30 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0        | 20 | PASS |
|               |      |      | NV | -30 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0        | 20 | PASS |
| 11N20SI<br>SO | Ant1 | 5180 | NV | -30 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|               |      | 5200 | NV | 50  | 0    | 0        | 20 | PASS |
|               |      |      | NV | -30 | 0    | 0        | 20 | PASS |
|               |      |      | NV | -20 | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | -10 | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 0   | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 10  | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 20  | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 30  | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 40  | 1000 | 0.192308 | 20 | PASS |
|               |      |      | NV | 50  | 1000 | 0.192308 | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|               |      |      |    |     |      |         |    |      |
|---------------|------|------|----|-----|------|---------|----|------|
|               |      | 5240 | NV | -30 | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | -20 | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | -10 | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 0   | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 10  | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 20  | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 30  | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 40  | 1000 | 0.19084 | 20 | PASS |
|               |      |      | NV | 50  | 1000 | 0.19084 | 20 | PASS |
|               |      | 5745 | NV | -30 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0       | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0       | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0       | 20 | PASS |
|               |      | 5785 | NV | -30 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0       | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0       | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0       | 20 | PASS |
|               |      | 5825 | NV | -30 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -10 | 0    | 0       | 20 | PASS |
|               |      |      | NV | 0   | 0    | 0       | 20 | PASS |
|               |      |      | NV | 10  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 20  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 30  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 40  | 0    | 0       | 20 | PASS |
|               |      |      | NV | 50  | 0    | 0       | 20 | PASS |
| 11N40SI<br>SO | Ant1 | 5190 | NV | -30 | 0    | 0       | 20 | PASS |
|               |      |      | NV | -20 | 0    | 0       | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

|                |      |      |    |     |   |   |    |      |
|----------------|------|------|----|-----|---|---|----|------|
|                |      |      | NV | -10 | 0 | 0 | 20 | PASS |
|                |      |      | NV | 0   | 0 | 0 | 20 | PASS |
|                |      |      | NV | 10  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 20  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 30  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 40  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 50  | 0 | 0 | 20 | PASS |
|                |      | 5230 | NV | -30 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -20 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -10 | 0 | 0 | 20 | PASS |
|                |      |      | NV | 0   | 0 | 0 | 20 | PASS |
|                |      |      | NV | 10  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 20  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 30  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 40  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 50  | 0 | 0 | 20 | PASS |
|                |      | 5755 | NV | -30 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -20 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -10 | 0 | 0 | 20 | PASS |
|                |      |      | NV | 0   | 0 | 0 | 20 | PASS |
|                |      |      | NV | 10  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 20  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 30  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 40  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 50  | 0 | 0 | 20 | PASS |
|                |      | 5795 | NV | -30 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -20 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -10 | 0 | 0 | 20 | PASS |
|                |      |      | NV | 0   | 0 | 0 | 20 | PASS |
|                |      |      | NV | 10  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 20  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 30  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 40  | 0 | 0 | 20 | PASS |
|                |      |      | NV | 50  | 0 | 0 | 20 | PASS |
| 11AC20S<br>ISO | Ant1 | 5180 | NV | -30 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -20 | 0 | 0 | 20 | PASS |
|                |      |      | NV | -10 | 0 | 0 | 20 | PASS |
|                |      |      | NV | 0   | 0 | 0 | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|  |  |      |    |     |      |          |    |      |
|--|--|------|----|-----|------|----------|----|------|
|  |  |      | NV | 10  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 20  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 30  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 40  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 50  | 0    | 0        | 20 | PASS |
|  |  | 5200 | NV | -30 | 0    | 0        | 20 | PASS |
|  |  |      | NV | -20 | 0    | 0        | 20 | PASS |
|  |  |      | NV | -10 | 0    | 0        | 20 | PASS |
|  |  |      | NV | 0   | 0    | 0        | 20 | PASS |
|  |  |      | NV | 10  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 20  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 30  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 40  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 50  | 0    | 0        | 20 | PASS |
|  |  | 5240 | NV | -30 | 0    | 0        | 20 | PASS |
|  |  |      | NV | -20 | 0    | 0        | 20 | PASS |
|  |  |      | NV | -10 | 0    | 0        | 20 | PASS |
|  |  |      | NV | 0   | 0    | 0        | 20 | PASS |
|  |  |      | NV | 10  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 20  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 30  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 40  | 0    | 0        | 20 | PASS |
|  |  |      | NV | 50  | 0    | 0        | 20 | PASS |
|  |  | 5745 | NV | -30 | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | -20 | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | -10 | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 0   | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 10  | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 20  | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 30  | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 40  | 1000 | 0.174064 | 20 | PASS |
|  |  |      | NV | 50  | 1000 | 0.174064 | 20 | PASS |
|  |  | 5785 | NV | -30 | 1000 | 0.172861 | 20 | PASS |
|  |  |      | NV | -20 | 1000 | 0.172861 | 20 | PASS |
|  |  |      | NV | -10 | 1000 | 0.172861 | 20 | PASS |
|  |  |      | NV | 0   | 1000 | 0.172861 | 20 | PASS |
|  |  |      | NV | 10  | 1000 | 0.172861 | 20 | PASS |
|  |  |      | NV | 20  | 1000 | 0.172861 | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdksign.cn

Web:  
www.gdksign.com

|                |      |      |    |     |      |          |    |      |
|----------------|------|------|----|-----|------|----------|----|------|
| 11AC40S<br>ISO | Ant1 | 5825 | NV | 30  | 1000 | 0.172861 | 20 | PASS |
|                |      |      | NV | 40  | 1000 | 0.172861 | 20 | PASS |
|                |      |      | NV | 50  | 1000 | 0.172861 | 20 | PASS |
|                |      |      | NV | -30 | 1000 | 0.171674 | 20 | PASS |
|                |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|                |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 50  | 0    | 0        | 20 | PASS |
|                |      | 5190 | NV | -30 | 0    | 0        | 20 | PASS |
|                |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|                |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 50  | 0    | 0        | 20 | PASS |
|                |      | 5230 | NV | -30 | 0    | 0        | 20 | PASS |
|                |      |      | NV | -20 | 0    | 0        | 20 | PASS |
|                |      |      | NV | -10 | 0    | 0        | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 50  | 0    | 0        | 20 | PASS |
|                |      | 5755 | NV | -30 | 1000 | 0.173762 | 20 | PASS |
|                |      |      | NV | -20 | 1000 | 0.173762 | 20 | PASS |
|                |      |      | NV | -10 | 1000 | 0.173762 | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0        | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0        | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0        | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com

|                |      |      |    |     |      |         |    |      |
|----------------|------|------|----|-----|------|---------|----|------|
|                |      | 5795 | NV | 50  | 0    | 0       | 20 | PASS |
|                |      |      | NV | -30 | 0    | 0       | 20 | PASS |
|                |      |      | NV | -20 | 0    | 0       | 20 | PASS |
|                |      |      | NV | -10 | 0    | 0       | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0       | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 50  | 0    | 0       | 20 | PASS |
| 11AC80S<br>ISO | Ant1 | 5210 | NV | -30 | 0    | 0       | 20 | PASS |
|                |      |      | NV | -20 | 0    | 0       | 20 | PASS |
|                |      |      | NV | -10 | 0    | 0       | 20 | PASS |
|                |      |      | NV | 0   | 0    | 0       | 20 | PASS |
|                |      |      | NV | 10  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 20  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 30  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 40  | 0    | 0       | 20 | PASS |
|                |      |      | NV | 50  | 0    | 0       | 20 | PASS |
|                |      | 5775 | NV | -30 | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | -20 | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | -10 | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 0   | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 10  | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 20  | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 30  | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 40  | 1000 | 0.17316 | 20 | PASS |
|                |      |      | NV | 50  | 1000 | 0.17316 | 20 | PASS |

TRF RF\_R1

Add: West Side of 1/F., Building C, Zone A, Fuyuan New Factory, Jiujiu Industrial Park,  
Minzhu, Shatou, Shajing, Bao'an District, Shenzhen, Guangdong, China

Tel: +(86) 0755-2985  
2678

Fax: +(86) 0755-2985  
2397

E-mail:  
info@gdkesign.cn

Web:  
www.gdkesign.com