Date: May 27, 2022

Re: § 2.933 Change in identification of equipment

To Whom It May Concern:
This change in identification of equipment request applies to the original FCC ID: 2ABU6-MS88SF2 ID, granted on 11/30/2018. The equipment bearing the modified identification (new FCC ID: 2A63Y-SQ88SF2) is electrically identical to the original equipment. Therefore, the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Ilan Tsafnat