


FCC ID: 2A64B-MR2508C



IC: 28593-MR2508C

Internal Photos





FCC ID: 2A64B-MR2508C

IC: 28593-MR2508C





FCC ID: 2A64B-MR2508C

IC: 28593-MR2508C



IC: 28593-MR2508C



顶部

摄像头

充电

电池

左驱动

右驱动


换片电机

核心板

抬起碰撞


Debug

RoHS
E23309
COP-1
W186V-DA
2521



FCC ID: 2A64B-MR2508C

IC: 28593-MR2508C



FCC ID: 2A64B-MR2508C



IC: 28593-MR2508C

Antenna





FCC ID: 2A64B-MR2508C

IC: 28593-MR2508C



FCC ID: 2A64B-MR2508C

IC: 28593-MR2508C



IC: 28593-MR2508C

