

出口 20200710- 警告 2020年8月10日 (8/10/2020) © 2020 玩具有限公司 警告 2020年8月10日 (8/10/2020) © 2020 玩具有限公司 警告 2020年8月10日 (8/10/2020) © 2020 玩具有限公司

360° SPINS!

FUNCTION

ROCKIN' WHEELS

FUNCTION

SWEEPING TAIL

FUNCTION

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

RC RADIO CONTROL

STUNT DINOSAUR

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

RC RADIO CONTROL

2.4GHz

360 DEGREE ROCK ROTATION

DUAL MOTOR DRIVING

ROCK AND ROLL STUNT FUN

STUNT DINOSAUR

RC RADIO CONTROL

LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

3+

YEARS

SWEEPING TAIL

FUNCTION

ROCKIN' WHEELS

FUNCTION

360° SPINS!

FUNCTION


LEFT AND RIGHT SHAKING TAIL. 360 DEGREE ROTATION.

STUNT DINOSAUR


RC RADIO CONTROL

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:(1) this device may not cause harmful interference, and(2) this device must accept any interference received, including interference that may cause undesired operation.NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions,may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
 - Increase the separation between the equipment and receiver.
 - Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.




WARNING: BATTERIES ARE TO BE INSERTED WITH THE CORRECT POLARITY (+ and -). DO NOT MIX DIFFERENT TYPES OF BATTERIES OR NEW AND USED BATTERIES. NON RECHARGEABLE BATTERIES ARE NOT TO BE RECHARGED. RECHARGEABLE BATTERIES ARE ONLY TO BE CHARGED UNDER ADULT SUPERVISION. RECHARGEABLE BATTERIES ARE TO BE REMOVED FROM THE TOY BEFORE BEING CHARGED. THE SUPPLY TERMINALS ARE NOT TO BE SHORT-CIRCUITED. REMOVE BATTERIES FROM THE TOY WHEN NOT IN USE FOR EXTENDED TIME OR WHEN BATTERIES BECOME EXHAUSTED. BATTERY INSTALLATION BY AN ADULT IS REQUIRED. DISPOSE OF BATTERIES RESPONSIBLY. DO NOT DISPOSE OF IN FIRE.



PRECAUCIONES: PELIGRO DE AHOGARSE. Contiene partes pequeñas. No recomendado para niños menores de 3 años.

WARNING: CHOKING HAZARD-Small parts. Not for children under 3 years.



MADE IN CHINA NO.9002

2.4GHz

FCC ID:2A838-9002

*Specifications Colours And Contents May Vary From Illustrations